

ADVANCE AUTO GARAGE

10 KAKI BUKIT ROAD 2 #01-21 FIRST EAST CENTRE
SINGAPORE 417868
TEL: 90079247

VEHICLE DETAILS

VEHICLE NO : SLZ8588P 2021 FEB
VEHICLE MODEL : BMW 216i GRAN TOURER
CHASSIS NO : WBA6V120605S73989

TP III

Ezlyna.

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>Dented</i>	1	\$ 1,292.00	\$ 1,292.00
2	REAR BUMPER SIDE HOLDER <i>new</i>	2	\$ 85.00	\$ 170.00
3	REAR BUMPER CENTRE MOULDING <i>at</i>	1	\$ 109.00	\$ 109.00
4	REAR BUMPER REINFORCEMENT <i>Dented</i>	1	\$ 589.00	\$ 589.00
5	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 76.00	\$ 152.00
6	REAR BUMPER INNER FRAME <i>could</i>	2	\$ 185.00	\$ 370.00
7	REAR BUMPER HANDS FREE MODULE <i>new</i>	1	\$ 586.00	\$ 586.00
8	REAR BUMPER HANDS FREE MODULE BRACKET <i>could</i>	1	\$ 219.00	\$ 219.00
9	REAR BUMPER TOW COVER <i>new</i>	1	\$ 43.00	\$ 43.00
10	REAR BUMPER SENSOR <i>2 pieces dented</i>	4	\$ 265.00	\$ 1,060.00
11	REAR BUMPER SENSOR HOLDER <i>new</i>	4	\$ 25.00	\$ 100.00
12	REAR END PANEL <i>new</i>	1	\$ 795.00	\$ 795.00
13	REAR END PANEL TOP GARNISH <i>new</i>	1	\$ 186.00	\$ 186.00
14	TAILLAMP <i>new</i>	2	\$ 541.00	\$ 1,082.00
15	TAILGATE <i>Dented</i>	1	\$ 1,615.00	\$ 1,615.00
16	TAILGATE LOCK <i>Dented</i>	1	\$ 297.00	\$ 297.00
17	TAILGATE WEATHERSTRIPE <i>at</i>	1	\$ 279.00	\$ 279.00
18	TAILGATE INNER TRIM BOARD <i>new</i>	1	\$ 529.00	\$ 529.00
19	TAILGATE REFLECTOR <i>new</i>	2	\$ 385.00	\$ 770.00
20	TAILGATE GLASS MOULDING <i>new</i>	1	\$ 188.00	\$ 188.00
21	BMW LOGO <i>3 new</i>	1	\$ 85.00	\$ 85.00
22	216i WORDING <i>3 new</i>	1	\$ 82.00	\$ 82.00
23	REAR EXHAUST PIPE <i>3 new</i>	1	\$ 1,167.00	\$ 1,167.00
24	REAR EXHAUST PIPE MOUNTING <i>new</i>	1	\$ 46.00	\$ 46.00
25	REAR EXHAUST PIPE GASKET <i>new</i>	1	\$ 38.00	\$ 38.00
26	REAR EXHAUST PIPE HEAT SHIELD <i>new</i>	1	\$ 192.00	\$ 192.00

TOTAL PRICE: \$ 12,041.00
LESS 5% \$ 602.05
SUB TOTAL PRICE: \$ 11,438.95

5755

5467.25

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 50.00	\$ 50.00
2	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00
3	REAR END PANEL SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
4	TAILGATE INNER TRIM BOARD CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
5	TAILGATE GLASS SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00

110

TOTAL : \$ 220.00

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,500.00	800	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	800	
3	WIRING CHECK	\$ 250.00	30	
4	TO APPLY TUFF COAT	\$ 200.00	30	
5	TO REMOVE REVERSE SENSOR	\$ 100.00	50	
6	TO REMOVE REAR CAMERA	\$ 100.00	50	
7	TO REMOVE REAR VIDEO RECORDER	\$ 100.00	50	
8	TO REMOVE UPHOLSTERY	\$ 150.00	30	
9	TO TRANSFER TAILGATE FITTINGS	\$ 150.00	80	
10	TO REMOVE TAILGATE GLASS	\$ 180.00	120	
11	TO REMOVE EXHAUST PIPE	\$ 150.00	X	
12	TO PERFORM DIAGNOSTIC TEST	\$ 200.00	150	

TOTAL: \$ 4,680.00

1790

ESTIMATE REPORT

TOTAL PARTS COST: \$ 11,658.95

TOTAL LABOUR COST: \$ 4,680.00

TOTAL REPAIR COST: \$ 16,338.95

Total: 7367.25

L/s: 5.9K.

0.4 Days

5.9K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: