


INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)
PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2001514315-01	Date of Loss:	21/04/2023
Vehicle Reg. No.:	SKP8611U	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHEN JINKANG		
Driver:	SIM YAN XI		
Make/Model:	PEUGEOT 5008, 1.6 (A)	Vehicle Reg. Date:	03/05/2018
Vehicle Colour:	WHITE		
Engine No:	10XTA40968478	Chassis No:	VF3MRHNYWJL017433
Odometer:	40000 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Present Location:	FALCON-AIR AUTO SERVICES PTE LTD (TAMPINES)		

COST OF CLAIMS

	Amount
Parts	3,197.80
Miscellaneous Items	0.00
Labour	1,650.00
Paintwork Labour	0.00
Towing	0.00
	Gross Total (\$)
	4,847.80
	+ GST 8.00% (\$)
	387.82
	Nett Amount (\$)
	5,235.62

This claim is handled by: JOSHUA NG
Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 25 Apr 2023)**Parts:** M1-MPV PEUGEOT 5008 1.6 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Falcon-Air Auto Services Pte Ltd/SKP8611U/25/04/2023 09:08**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*N/S REAR DOOR PROTECTOR	0.00	0.00	*458.00 F
2	1		*N/S REAR DOOR PROTECTOR CLIPS	0	0.00	*60.00 FS
3	1		*N/S REAR WHEEL ARCH GARNISH	0.00	0.00	*465.00 F
4	1		*N/S REAR WHEEL ARCH GARNISH CLIPS	0	0.00	*60.00 FS
5	1		*N/S REAR RIM	0.00	0.00	*1,350.00 F
6	1		*N/S REAR SHOCK ABSORBER	0.00	0.00	*240.00 F
7	1		*N/S REAR WHEEL BEARING	0.00	0.00	*285.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	2,918.00
+ Margin on L,N Items 10.00% (S\$)	279.80
Total Parts (S\$)	3,197.80

Falcon-Air Auto Services Pte Ltd/SKP8611U/25/04/2023 09:08. Not valid without Reference section.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO FIT TYRE ON NEW RIM PLUS BALANCING	New	50.00
2	TO REPLACE N/S REAR UNDERCARRIAGE	New	280.00
3	TO CONDUCT 4 WHEEL COMPUTERISE WHEEL ALIGNMENT	New	120.00
4	TO REPAIR INNER PANEL, ACCIDENT DAMAGE AREA, REPLACEMENT OF PARTS AND ALIGN THE SAME	New	600.00
5	TO PUTTY AND SPRAY PAINT ON ACCIDENT DAMAGE AREA	New	600.00
Gross Labour Cost (S\$)			1,650.00

Falcon-Air Auto Services Pte Ltd/SKP8611U/25/04/2023 09:08. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

FALCON-AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-08/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg