

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: JANICE KOH

Date: 28 Apr 2023

**Preliminary Advice**

Vehicle No	: SKP8611U	Accident Date	: 21/04/2023
Make	: PEUGEOT 5008	Policy No.	: SP2001514315-01
Assignment Date	: 25/04/2023	Excess	: S\$600.00
Date of Inspection	: 28/04/2023	Est. Duration of Repair	: 3
Inspection At	: FALCON-AIR AUTO SERVICES PTE LTD (TAMPINES) BLK 9006 #01-200 TAMPINES ST 93 SINGAPORE		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,847.80
Revised Amount	:S\$	3,330.30
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,330.30

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	105,000.00
COE / PARF Rebate	:S\$	41,236.00
Salvage Value	:S\$	
Margin for Repair	:S\$	63,764.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments :The vehicle repair on part by parts basis.  
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.