



FALCON-AIR

FALCON-AIR AUTO SERVICES PTE LTD
CO. REG. No.: 1995-01140-D

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM			
Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	SP2001514315-01	Date of Loss:	21/04/2023
Vehicle Reg. No.:	SKP8611U	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHEN JINKANG		
Driver:	SIM YAN XI		
Make/Model:	PEUGEOT 5008, 1.6 (A)	Vehicle Reg. Date:	03/05/2018
Vehicle Colour:	White		
Engine No:	10XTA40968478	Chassis No:	VF3MRHNYWJL017433
Odometer:	40000 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Present Location:	FALCON-AIR AUTO SERVICES PTE LTD (TAMPINES)		

COST OF CLAIMS	Amount
Parts	3,197.80
Miscellaneous Items	0.00
Labour	1,650.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	4,847.80
+ GST 8.00% (S\$)	387.82
Nett Amount (S\$)	5,235.62

This claim is handled by: JOSHUA NG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Apr 2023)
Parts: M1-MPV PEUGEOT 5008 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Falcon-Air Auto Services Pte Ltd/SKP8611U/25/04/2023 09:08
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*N/S REAR DOOR PROTECTOR	0.00	0.00	*458.00 F <i>cut</i>
2	1		*N/S REAR DOOR PROTECTOR CLIPS	0	0.00	*60.00 FS <i>req</i>
3	1		*N/S REAR WHEEL ARCH GARNISH	0.00	0.00	*465.00 F <i>cut</i>
4	1		*N/S REAR WHEEL ARCH GARNISH CLIPS	0	0.00	*60.00 FS <i>req</i>
5	1		*N/S REAR RIM	0.00	0.00	*1,350.00 F <i>cut</i>
6	1		*N/S REAR SHOCK ABSORBER	0.00	0.00	*240.00 F X
7	1		*N/S REAR WHEEL BEARING	0.00	0.00	*285.00 F X

F=Franchise part. S=SpcNett.

Sub Total (S\$)	2,918.00
+ Margin on L,N Items 10.00% (S\$)	279.80
Total Parts (S\$)	3,197.80

Falcon-Air Auto Services Pte Ltd/SKP8611U/25/04/2023 09:08. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO FIT TYRE ON NEW RIM PLUS BALANCING	New	30 50.00
2	TO REPLACE N/S REAR UNDERCARRIAGE	New	X 280.00
3	TO CONDUCT 4 WHEEL COMPUTERISE WHEEL ALIGNMENT	New	80 120.00
4	TO REPAIR INNER PANEL, ACCIDENT DAMAGE AREA, REPLACEMENT OF PARTS AND ALIGN THE SAME	New	300 600.00
5	TO PUTTY AND SPRAY PAINT ON ACCIDENT DAMAGE AREA	New	300 600.00
Gross Labour Cost (\$\$)			1,650.00

Falcon-Air Auto Services Pte Ltd/SKP8611U/25/04/2023 09:08. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Not Authorise
Ex \$600
3 days
Resury new parts

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: