



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading

Dealing in New/Used Cars, Hire Purchase & Insurance.



INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2003708419	Date of Loss:	16/04/2023
Vehicle Reg. No.:	SFU8889T	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	KEE KOH LEONG		
Make/Model:	TOYOTA HARRIER, 2.0 M GRADE (A)	Vehicle Reg. Date:	07/01/2019
Vehicle Colour:	WHITE	Chassis No:	JTEZB3GH30J004158
Engine No:	8ARZ148496		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		

Present Location: MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)

COST OF CLAIMS	Amount
Parts	4,845.50
Miscellaneous Items	0.00
Labour	2,330.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	7,175.50
+ GST 8.00% (S\$)	574.04
Nett Amount (S\$)	7,749.54

This claim is handled by: BILLY

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Apr 2023)
 Parts: M1-SUV TOYOTA HARRIER 2.0 M GRADE (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-dominant Standard List)
 Print Code: Mova Automotive Pte Ltd/SFU8889T/26/04/2023 09:43
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT FENDER RH	0.00	0.00	*380.00 F	BUC ✓
2	1		*FRONT FENDER COWLING RH	0.00	0.00	*185.00 F	DIS ✓
3	10		*FRONT FENDER COWLING CLIPS 2.00 x 10 Pcs = 20.00	0.00	0.00	20.00 *25.00 F	NEC ✓
4	1		*FRONT SPORT RIM RH	0.00	0.00	*1,680.00 F	CUT ✓
5	1		*FRONT WHEEL HUB RH BEARING	0.00	0.00	*250.00 F	? X
6	1		*FRONT KNUCKLE ARM RH	0.00	0.00	*240.00 F	X NN X
7	1		*FRONT LOWER ARM RH	0.00	0.00	*220.00 F	X NN X
8	1		*FRONT DOOR RH	0.00	0.00	*720.00 F	BUC ✓
9	1		*FRONT DOOR STICKER RH	0.00	0.00	*90.00 F	NEC ✓
10	1		*FRONT DOOR CHROME MOULDING RH	0.00	0.00	*125.00 F	CUT ✓
11	1		*FRONT DOOR PILLAR RH (REPAIR)	0.00	0.00	-	
12	1		*REAR DOOR RH (REPAIR)	0.00	0.00	-	
13	1		*REAR DOOR CHROME MOULDING RH	0.00	0.00	*90.00 F	CUT ✓
14	1		*ROCKER PANEL GARNISH RH	0.00	0.00	*400.00 F	X NN
						Sub Total (\$\$)	4,405.00 3290.00
						+ Margin on L,N Items 10.00% (\$\$)	440.50 329.00
						Total Parts (\$\$)	4,845.50 3619.00

F=Franchise part.

Mova Automotive Pte Ltd/SFU8889T/26/04/2023 09:43. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

SUPPLEMENTARY: > 1x FRONT DOOR CHROME STICKER RH @ 35.00 x 2 = 70.00 ✓

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO KNOCK & STRAIGHTEN FRONT DOOR PILLAR RH, REMOVE & REPLACE ACCIDENT DAMAGED PARTS, REALIGN ALL CONNECTION	New	600.00 400 ✓
2	SPRAY PAINT FRONT FENDER RH, FRONT DOOR PILLAR RH, FRONT DOOR RH, REAR DOOR RH. (PEARL COLOUR)	New	1,400.00 800 ✓
3	REMOVE & REPLACE FRONT DOOR INNER TRIM, MECHANISM & CHECK LOCKING SYSTEM	New	60.00 ✓
4	REMOVE & REPLACE FRONT DOOR PILLAR GARNISH RH, COVERING TRIM	New	60.00 ✓
5	REMOVE & REPLACE FRONT UNDER CARRIAGE SUSPENSION RH	New	150.00 ✓
6	COMPUTER WHEEL ALIGNMENT	New	60.00 ✓
Gross Labour Cost (S\$)			2,330.00 1320.00

Mova Automotive Pte Ltd/SFU8889T/26/04/2023 09:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

- Not authorise.
 - Excess = \$? (TBA)
 - Resurvey before paid for P/P repair.
 - Survey by Simon Ho (62563561)

1) PARTS 3619.00
 2) LABOUR 1320.00
 3) SUPPLEMENT 77.00
 5016.00 PBP

PLEASE ADVISE.

THANK YOU

BENJ UAW.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

UEN No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: MOVA AUTOMOTIVE PTE LTD

BLK 1008 #01-04
BUKIT MERAH LANE 3
SINGAPORE 159722
SFU8889T
BILLY

NO: DLI9263525
PAGE: 1
DATE: 17/05/2023
A/C CODE: LDMV315
TERMS: CR
P/O NO: SFU8889T

VEH NO: SFU8889T

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1 TS3811-48210	1. FR FENDER RH	DB1D15	1	380.00	380.00
2 TS3875-48120	2. FENDER LINER FR RH	DBEE11	1	185.00	185.00
3 T90467-07201	3. CLIP.COWLING	DD1A168	10	2.00	20.00
4 T42611-48A10	4. SPORT RIM 18"	DB1HS	1	1,680.00	1,680.00
5 T67001-48150	5. DOOR FR RH	DBEE3	1	720.00	720.00
6 T75921-48050	6. TAPE FR RH	DDS	1	90.00	90.00
7 T75710-48080	7. OUTER MLG FR RH	DUIF22-9	1	125.00	125.00
8 T75730-48070	8. OUTER MLG RR RH	DUIF23-7	1	90.00	90.00
TOTAL QUANTITY:			17	TOTAL	SIN 3,290.00
				ADD GST @ 8%	263.20
				GRAND TOTAL	SIN 3,553.20

15 FAN YOONG RD

Print / MT / 17/05/2023 10:42:57 AM

SALESMAN: MT

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E. & O. E

GOODS RECEIVED BY





合興汽車零件私人有限公司 HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403
TEL: 6291 2827 FAX: 6296 4390
A/C: 6291 1886 FAX: 6291 7717
UEN No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: MOVA AUTOMOTIVE PTE LTD

BLK 1008 #01-04
BUKIT MERAH LANE 3
SINGAPORE 159722
SFU8889T
BILLY

NO: DLI9263773
PAGE: 1
DATE: 24/05/2023
A/C CODE: LDMV315
TERMS: CR
P/O NO: SFU8889T

VEH NO: SFU8889T

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
① T75968-48020	TAPE	DDS	1	35.00	35.00
② T75929-48020	TAP BLACK OUT LEX	DDS	1	35.00	35.00
TOTAL QUANTITY:			2	TOTAL	SIN 70.00
				ADD GST @ 8%	5.60
				GRAND TOTAL	SIN 75.60

15 FAN YOONG RD

Print / MT / 24/05/2023 10:04:12 AM

SALESMAN: MT

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E. & O. E.

GOODS RECEIVED BY



PAYNOW UEN No.
200310923R