



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : HSBC LIFE (SINGAPORE) PTE LTD

DATE: 23/5/2023

### Survey details

Date of loss	24/4/2023
Date of appointment	26/4/2023
Date of survey	27/4/2023
Location of survey	HARMONY MOTOR (AMK) PTE LTD

### Vehicle Details:

Claim Type:	THIRD PARTY
Vehicle number	SGE 6060C
Make and Model	TOYOTA HARRIER G GRADE
Date of registration	28/8/2019
Excess	
Market Value	\$137,000.00
Parf Rebate	\$54,057.00
Nett Loss	\$82,943.00

### Repair details

Initial Estimate	
------------------	--

### Proposed/Revised repair cost:

Parts	
"Check items (Estimated)	
Labour	
Total	
Lump Sum (Estimated)	
Number of days of repair	4 days (est)

### **Remarks:**

Daamges Consistent

The estimated repair cost of the damaged vehicle is  
in the region of \$6,000.00-\$7,000.00