



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI23004308/Aqy3m4	
			Date: 14/06/2023	
			Code: UOI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	YQ 5361P	Veh. Inspected	SMK 2246H
	Policy No.		Coverage (\$)	0.00
	Claim No.	M12D00092301	Excess (\$)	0.00
	Assign From	JOANNE YONG	Assign Date	26/04/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	MERCEDES BENZ C 200	c.c	1796
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	WDD2040482A382659	Colour	SILVER
	Odometer	164067 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	225/40R18	MICHELIN	6 mm
	L/H Front Tyre	225/40R18	MICHELIN	6 mm
	R/H Rear Tyre	225/40R18	MICHELIN	6 mm
	L/H Rear Tyre	225/40R18	MICHELIN	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	22/12/2022	Inspection Date	16/05/2023
	Survey held at	25 KAKI BUKIT ROAD 4 #05-26 SYNERGY @ KB S 417800		
	Repairer	LC AUTOMOTIVE		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	