

LC AUTOMOTIVE

25 KAKI BUKIT ROAD 4 #05-26 Synergy @ KB Singapore 417800

TP 401
Xiao Chan.

YAP SIEW PING
25 KAKI BUKIT ROAD4
05-26 SYNERGY @KB
Singapore 417800

15th MAY 2023

WDD2040482 A 382659

Accident date: 22th DECEMBER 2022

Estimated repair cost for vehicle no: SMK2246H MERCEDES BENZ C200

S/n	Qty	Items/Nett	U/price	Amount
1	1	Head lamp assy <i>curled</i>		\$2,955.00
2	1	headlamp washer cover RH <i>Miscan</i>		\$125.00
3	1	front bumper energy absorber <i>curled</i>		\$255.00
4	4	front bumper side carrier -RH <i>curled</i>		\$180.00
5	1	Front radiator grille emblem logo (Mercedes star) <i>in</i>		\$485.00
6	1	Front radiator grille assy <i>curled</i>		\$1,442.00
7	1	Front bumper center grille <i>curled</i>		\$255.00
8	1	Front bumper <i>Distorted</i>		\$1,885.00
9	2	Front Bumper support Bracket L/R <i>2nd RH</i>	\$115.00	\$230.00
10	1	Front bumper reinforcement <i>not in</i>		\$1,070.00

Subtotal :- \$8,882.00

S/n	Qty	S/Nett Item	U/price	Amount
1	2	front bumper sensor RH <i>changed</i>	\$250.00	\$500.00
2	1	front bumper clips <i>in</i>		\$75.00
3	1	front bumper mount lamp RH <i>not in</i>		\$355.00
4	1	front bumper mount lamp brace RH <i>3rd in</i>		\$98.00
5	1	Front Bumper tow eye cap RH		\$90.00
6	1	front bumper side grille RH <i>not in</i>		\$189.00

Subtotal :- \$1,307.00

Labour charges

Tuff kote

To Check Wiring System

To diagnostic check & reset

Panel beating

Spray painting

- hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

970 \$120.00

Adrian Lj \$60.00

H/S 16/05/23. \$380.00

04 Days \$900.00

\$800.00

Subtotal :- \$2,260.00

Total:- \$12,449.00

total: 6864.90

4/5: 5.5K

(5.5K)