

1 KAKI BUKIT AVENUE 6
#01-82 AUTOBAY SINGAPORE 417883

#01-82 AUTOBAY SINGAPORE 417883

: NSP1707038720

Xiao Chen

CLAIM DETAILS: PARTS		QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE LAMP <i>Cracked</i>	2	\$ 79.10	\$ 158.20
2	REAR BUMPER <i>Dehd</i>	1	\$ 678.10	\$ 678.10
3	REAR BUMPER SIDE HOLDER <i>new</i>	2	\$ 45.20	\$ 90.40
4	REAR BUMPER REFLECTOR <i>NE new</i>	2	\$ 80.50	\$ 161.00
5	REAR BUMPER CENTRE PAD <i>Dehd</i>	1	\$ 225.40	\$ 225.40
6	REAR BUMPER SIDE PAD <i>LH Dehd</i>	2	\$ 127.50	\$ 255.00
7	REAR BUMPER SPONGE <i>Cracked</i>	1	\$ 54.10	\$ 54.10
8	REAR BUMPER MUD SHIELD <i>form</i>	2	\$ 67.70	\$ 135.40
9	REAR END PANEL OUTER <i>3 Distorted</i>	1	\$ 689.50	\$ 689.50
10	REAR END PANEL INNER	1	\$ 433.80	\$ 433.80
11	REAR END PANEL TOP GARNISH <i>Cracked</i>	1	\$ 195.20	\$ 195.20
12	REAR END PANEL ANTENNA SENSOR <i>Dnd</i>	1	\$ 190.50	\$ 190.50
13	TAILLAMP <i>LH cut, RH Cracked</i>	2	\$ 450.10	\$ 900.20
14	TAILLAMP PANEL <i>RH Distorted</i>	2	\$ 407.20	\$ 814.40
15	TAILLAMP LOWER BRACKET <i>Cracked</i>	2	\$ 55.20	\$ 110.40
16	TAILGATE <i>Distorted</i>	1	\$ 1,245.10	\$ 1,245.10
17	TAILGATE LOCK <i>Tamed</i>	1	\$ 372.90	\$ 372.90
18	TAILGATE LOCK HANDLE <i>the new</i>	1	\$ 240.40	\$ 240.40
19	TAILGATE WEATHERSTRIPE <i>cut</i>	1	\$ 329.50	\$ 329.50
20	TAILGATE INNER PULL POCKET <i>Dehd</i>	1	\$ 45.60	\$ 45.60
21	TAILGATE HINGE <i>new</i>	2	\$ 86.50	\$ 173.00
22	TAILGATE DAMPER <i>Dnd</i>	2	\$ 280.10	\$ 560.20
23	TAILGATE OUTER GARNISH <i>Cracked</i>	1	\$ 257.30	\$ 257.30
24	TAILGATE INNER TRIM COVER <i>Dehd</i>	1	\$ 195.90	\$ 195.90
25	TAILGATE REFLECTOR <i>Cracked</i>	2	\$ 385.10	\$ 770.20
26	TAILGATE WIPER MOTOR <i>Dnd</i>	1	\$ 581.70	\$ 581.70
27	TAILGATE WIPER ARM <i>new</i>	1	\$ 185.80	\$ 185.80
28	TAILGATE WIPER ARM COVER <i>new</i>	1	\$ 24.10	\$ 24.10
29	TAILGATE GLASS MOULDING <i>new</i>	1	\$ 130.20	\$ 130.20
30	TOYOTA LOGO <i>new</i>	1	\$ 75.30	\$ 75.30
31	REAR FENDER INNER TRIM BOARD <i>Cracked</i>	2	\$ 699.10	\$ 1,398.20
32	REAR FENDER OUTER GARNISH <i>Repair</i>	2	\$ 322.90	\$ 645.80
33	SPARE TYRE PANEL <i>Buckled</i>	1	\$ 1,055.40	\$ 1,055.40
34	SPARE TYRE PANEL TOP BOARD OUTER <i>Dehd</i>	1	\$ 349.90	\$ 349.90
35	SPARE TYRE PANEL TOP BOARD INNER <i>Deformed</i>	1	\$ 488.30	\$ 488.30
36	TOOLS TRAY <i>Dehd</i>	1	\$ 332.50	\$ 332.50
37	REAR EXHAUST PIPE <i>Best</i>	1	\$ 514.70	\$ 514.70
38	REAR EXHAUST PIPE MOUNTING <i>the new</i>	1	\$ 35.90	\$ 35.90

39	REAR EXHAUST PIPE GASKET <i>new</i>	1	\$ 34.20	\$ 34.20
40	REAR EXHAUST HEAT SHIELD <i>Bent.</i>	1	\$ 90.80	\$ 90.80

13133.40
9850.05

TOTAL PRICE: \$ 15,224.50
LESS 25% \$ 3,806.12
SUB TOTAL PRICE: \$ 11,418.38

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE <i>Bent</i>	1	\$ 30.00	\$ 30.00
2	REAR BUMPER PLATE HOLDER <i>new</i>	1	\$ 30.00	\$ 30.00
3	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
4	REAR BUMPER MUD SHIELD CLIPS	2 SET	\$ 20.00	\$ 40.00
5	REVERSE SENSOR <i>new</i>	1 SET	\$ 280.00	\$ 280.00
6	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00
7	REAR END PANEL SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
8	TAILGATE OUTER GARNISH CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00
9	TAILGATE INNER TRIM COVER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
10	TAILGATE GLASS SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
11	REAR CAMERA <i>new</i>	1	\$ 480.00	\$ 480.00
12	REAR FENDER INNER SHIELD CLIPS <i>new</i>	2 SET	\$ 30.00	\$ 60.00
13	REAR FENDER OUTER GARNISH CLIPS <i>new</i>	2 SET	\$ 30.00	\$ 60.00
14	SPARE TYRE PANEL SEALANT <i>new</i>	1 SET	\$ 60.00	\$ 60.00

Rear Fender Inner Trim clips

new TOTAL: *60* \$ 1,260.00

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,800.00	<i>1200</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	<i>1000</i>	
3	W RING CHECK	\$ 100.00	<i>30</i>	
4	TO APPLY TUFF COAT	\$ 150.00	<i>80</i>	
5	TO REMOVE UPHOLSTY & REAR SEAT	\$ 280.00	<i>100</i>	
6	TO REMOVE REVERSE SENSOR	\$ 100.00	<i>50</i>	
7	TO REMOVE REAR CAMERA	\$ 100.00	<i>50</i>	
8	TO REMOVE REAR VIDEO RECORDER	\$ 100.00	<i>50</i>	
9	TO REMOVE TAILGATE GLASS	\$ 180.00	<i>120</i>	
10	TO TRANSFER TAILGATE FITTINGS	\$ 150.00	<i>60</i>	
11	TO REMOVE EXHAUST PIPE	\$ 150.00	<i>60</i>	

TOTAL: \$ 4,910.00

2800

ESTIMATE REPORT

TOTAL PARTS COST: \$ 12,678.38

TOTAL LABOUR COST: \$ 4,910.00

TOTAL REPAIR COST: \$ 17,588.38

APPROVED DETAILS

SURVEYOR:

CONTACT:

PART BY PART / LUMP SUM:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FAX:

Total: 1367005

L/S: 10 SK.

09 Days