

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard  
#04-01 Suntec Tower Three  
Singapore 038988From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Foo Ai Ngho

Date: 27 Apr 2023

**Preliminary Advice**

Vehicle No	: SND8430C	Accident Date	: 25/04/2023
Make	: HYUNDAI AD AVANTE	Policy No.	: DMPG23001918
Assignment Date	: 26/04/2023	Excess	: S\$500.00
Date of Inspection	: 27/4/2023	Est. Duration of Repair	: 6
Inspection At	: FALCON-AIR AUTO SERVICES PTE LTD (HQ)		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,735.40
Revised Amount	:S\$	5,575.80
Check Items (Estimated)	:S\$	83.60
Total	:S\$	5,659.40

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	124,000.00
COE / PARF Rebate	:S\$	50,068.00
Salvage Value	:S\$	
Margin for Repair	:S\$	73,932.00

**Remarks**

( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments : Part by part repair

Please note that the preliminary advise amount (Revised &amp; Check items) stated are subject to consistency check, part prices and labour cost .

According to surveyor, damages did not looks like park and found, likely hit onto railing. Suggest to do investigation.

Kindly advised.