

R/S 19/8

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 26 Apr 2023)
Parts: 143 **HYUNDAI AD AVANTE 1.6 GLS S (A)** (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Falcon-Air Auto Services Pte Ltd/SND8430C/26/04/2023 15:58
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BUMPER	R 0.00	0.00	*285.00 F	L
2	1		*FRONT BUMPER CLIPS	MR 0	0.00	*60.00 FS	L
3	1		*FRONT BUMPER LOGO	MR 0.00	0.00	*35.00 F	L
4	1		*FRONT RADIATOR GRILLE	CM 0.00	0.00	*185.00 F	L
5	1		*FRONT BUMPER LOWER GRILLE	CM 0.00	0.00	*115.00 F	L
6	1		*FRONT BUMPER AIRDUCT	CM 0.00	0.00	20.00 *25.00 F	L
7	1	X	*FRONT BUMPER TOP	R 0.00	0.00	*95.00 F	X
8	1		*FRONT BUMPER SIDE RETAINER RH	DIT 0.00	0.00	*28.00 F	L
9	1		*RH HEADLAMP	CM 0.00	0.00	*750.00 F	L
10	1		*RH FRONT FENDER	R 0.00	0.00	*410.00 F	L
11	1		*RH FRONT FENDER UNDERSHIELD	DIT 0.00	0.00	*65.00 F	L
12	1		*RH FRONT FENDER UNDERSHIELD CLIPS	MR 0	0.00	*40.00 FS	L
13	1		*RH FRONT DOOR	R 0.00	0.00	*850.00 F	L
14	1	X	*RH FRONT DOOR TOP HINGE		0.00	*38.00 F	L
15	1	X	*RH FRONT DOOR LOWER HINGE		0.00	*38.00 F	L
16	1		*RH FRONT DOOR GARNISH	MR 0.00	0.00	*30.00 F	L
17	1	X	*RH FRONT DOOR INNER SEAL	MR 0.00	0.00	*65.00 F	X

F=Franchise part. S=SpcNett.

Sub Total (S\$)	3,114.00
+ Margin on L,N Items 10.00% (S\$)	301.40
Total Parts (S\$)	3,415.40

Falcon-Air Auto Services Pte Ltd/SND8430C/26/04/2023 15:58. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

RH Headlamp support

CM 28 ✓

REPAIR DETAILS

SUPPLEMENTARY

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Jun 2023)

Parts: 143 HYUNDAI AD AVANTE 1.6 GLS S (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Falcon-Air Auto Services Pte Ltd/SND8430C/20/06/2023 13:01

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*RH HEADLAMP SUPPORT	0.00	0.00	*28.00 F
Sub Total (\$\$)						28.00
+ Margin on L,N Items 10.00% (\$\$)						2.80
Total Parts (\$\$)						30.80

Falcon-Air Auto Services Pte Ltd/SND8430C/20/06/2023 13:01. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO FOCUS HEADLAMP/ CHECK LIGHT SYSTEM	New	50.00
2	COMPUTERISED WHEEL ALIGNMENT	New	120.00
3	TO TRANSFER FRONT DOOR PARTS	New	100.00
4	TO REPAIR/ RESPRAY RH FRONT SPORTS RIM	New	200.00
5	TO REPAIR BONNET , RH ROCKER PANEL, RH REAR DOOR , RH REAR FENDER, REAR BUMPER INCLUDES REPLACEMENT OF PARTS	New	850.00
6	TO SPRAY PAINTING BONNET, FRONT BUMPER, FRONT BUMPER TOP, RH FRONT FENDER, RH FRONT DOOR, RH REAR DOOR, RH ROCKER PANEL, REAR BUMPER	New	2,000.00
Gross Labour Cost (\$\$)			3,320.00

Falcon-Air Auto Services Pte Ltd/SND8430C/26/04/2023 15:58. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg

PARTS: 2,801.00
+10% 280.10
3,081.10
SN: 100.00
LABOUR: 2,420.00
5,601.10
LESS EXCESS - 500.00
FINAL 5,101.10