

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0391/2023/EQ
DATE : 21-Apr-23
WIP : 17413

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 25/4/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Rasul

*12 days exclude 2
Johnny Boo 19 Jul*

OWNER'S NAME : MR SADAT QAYYUM
ADDRESS : 30 MOUNT ELIZABETH HIGHPOINT
#03-30
SINGAPORE 228519
TELEPHONE : HP +65 93252488
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : -
VEHICLE NO : **SNA 7786 Z**
MODEL CODE : AUDI A6 DESIGN 2.0 TFSI S
MODEL YEAR : 31/5/2021
ENGINE NO : DKY 015489
CHASSIS NO : WAUZZZF24MN071864
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Apr-23
PLACE OF ACCIDENT : 63 MARKET STREET, B2 (BANK OF SINGAPORE CENTRE)

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 7786 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
	<i>c/f</i>		\$ 4,760.00
7	TO DISMANTLE AND RENEW REAR BUMPER. TO REMOVE AND REINSTALL LHS SILL PANEL TRIM. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 6,400.00	\$ 3,000.00
8	TO RESPRAY REAR BUMPER, LHS REAR FENDER, DRAIN CHANNEL, LHS SILL PANEL, DOOR ENTRANCE, ROOF CHANNEL AND REAR END PANELLING.	\$ 5,500.00	\$ 2,475.00
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 16,852.00	\$ 10,427.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 7786 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1 \$	3,187.00 \$	2,549.60
2	REAR BUMPER FIXING PARTS	1 \$	259.00	
3	REAR BUMPER SPOILER	1 \$	1,043.00	
4	REAR BUMPER TRIM - LH	1 \$	289.00	
5	REAR BUMPER SECURING STRIP	1 \$	204.00 \$	162.80
6	REAR BUMPER GUIDE SECTION - LH LOWER	1 \$	75.00	
7	REAR BUMPER GUIDE SECTION - LH UPPER	1 \$	54.00	
8	REAR BUMPER GUIDE PROFILE - LH	1 \$	79.00	
9	REAR VENT	1 \$	502.00	
10	REAR SIDE PANEL - LH	1 \$	5,559.00 \$	4,447.20
11	REAR DOOR STONE CHIP PROTECTION FILM - LH	1 \$	146.00	
12	REAR WINDOW HEATED	1 \$	1,385.00 \$	1,108.00
13	REAR QUARTER WINDOW - LH	1 \$	834.00 \$	667.20
14	WINDOW PRIMER	2 \$	47.00 \$	37.60
15	REAR WHEEL HOUSING LINER - LH	1 \$	322.00	
16	ATTACHMENT PARTS	1 \$	144.00 \$	115.20
17	ADHESIVE TAPES	1 \$	68.00	
18	REAR BUMPER REFLECTOR - LH OUTER	1 \$	49.00	
19	REAR BUMPER REFLECTOR - LH INNER	1 \$	36.00	
20	REAR PARKING AID SENSOR - INNER	1 \$	299.00	
SUB TOTAL SPARE PARTS		:	\$ 14,581.00	\$ 9,087.60

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 7786 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		c/f		\$
21	REAR PARKING AID SEAL RING	4 \$	11.00	9,087.60
22	REAR PARKING AID SENSOR - OUTER	1 \$	299.00	
23	ACRYLIC SEALANT	S/N \$	180.00	\$ 180.00
24	CAVITY WAX	S/N \$	140.00	\$ 140.00
25	STONE CHIP	S/N \$	180.00	\$ 180.00
26	METAL FILLER POWDER	S/N \$	280.00	\$ 280.00
27	1/4 GLASS SEALANT	S/N \$	100.00	\$ 100.00
28	REAR WINSCREEN SEALANT	S/N \$	200.00	\$ 200.00
29	SUNDRIES	\$	500.00	\$ 35.20
TOTAL SPARE PARTS		:	\$ 16,471.00	\$ 10,202.80
TOTAL LABOUR CHARGES		:	\$ 16,852.00	\$ 10,427.00
GRAND TOTAL		:	\$ 33,323.00	\$ 20,629.80

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bi-13/07/23