

(08/13) wof

ASS. REC. BY: 702

REF:

564H

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ TP/WS/TP RES/OD RES/EVA/INV/MVTo Inspect Vehicle No: SNA 7786Zat Workshop m/s PREMIUMof ALEXANDRA RDInsured: ALH

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: TBA

(Client's Record)

Make of Veh: _____

(Policy Condition) 2pmRemark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 195K

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SNA 7786Z Yr Regn: 2021 MAYType: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A6 DESIGN 2.0 TFSI S c.c. 1984Colour: BLUE A/C: Insured / Std / NI / NASp. Reading: 13258 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAU ZZZF24MN 071864

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: NII / ☒ S/Rim / STD A/Rim orTyre Size: F: 225/55R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 18/04/23

Survey held at

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 26/04/23

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

H/S REAR

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 108K

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

) S + RS, SI

) Photos

) Others

Report Format : _____

Lump Sum / I.B.I. (\$) _____)

TOTAL



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0391/2023/EQ
DATE : 21-Apr-23
WIP : 17413

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 25/4/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR SADAT QAYYUM
ADDRESS : 30 MOUNT ELIZABETH HIGHPOINT
#03-30
SINGAPORE 228519
TELEPHONE : HP +65 93252488
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : -
VEHICLE NO : **SNA 7786 Z**
MODEL CODE : AUDI A6 DESIGN 2.0 TFSI S
MODEL YEAR : 31/5/2021
ENGINE NO : DKY 015489
CHASSIS NO : WAUZZZF24MN071864
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Apr-23
PLACE OF ACCIDENT : 63 MARKET STREET, B2 (BANK OF SINGAPORE CENTRE)

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 7786 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$	360.00	/
2	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,600.00	/
3	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,600.00	/
4	TO RENEW REAR WINDSCREEN AND LHS 1/4 GLASS TO FACILITATE RENEWAL LHS REAR FENDER.	S/N \$	600.00	/
5	TO INSTALL SOLAR FILM FOR ALL AFFECTED GLASSES.	S/N \$	400.00	/
6	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$	200.00	/
TOTAL LABOUR CHARGES		:	\$ 4,760.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 7786 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO DISMANTLE AND RENEW REAR BUMPER. TO REMOVE AND REINSTALL LHS SILL PANEL TRIM. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	@500x6 \$ 6,400.00	3000
8	TO RESPRAY REAR BUMPER, LHS REAR FENDER, DRAIN CHANNEL, LHS SILL PANEL, DOOR ENTRANCE, ROOF CHANNEL AND REAR END PANELLING.	@550x45 \$ 5,500.00	2475
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 16,852.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 7786 Z

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS
1	REAR BUMPER <i>de</i>	1	\$	3,187.00	
2	REAR BUMPER FIXING PARTS <i>X</i>	1	\$	259.00	
3	REAR BUMPER SPOILER <i>X</i>	1	\$	1,043.00	
4	REAR BUMPER TRIM - LH <i>X</i>	1	\$	289.00	
5	REAR BUMPER SECURING STRIP <i>new</i>	1	\$	204.00	
6	REAR BUMPER GUIDE SECTION - LH LOWER <i>?</i>	1	\$	75.00	
7	REAR BUMPER GUIDE SECTION - LH UPPER <i>?</i>	1	\$	54.00	
8	REAR BUMPER GUIDE PROFILE - LH <i>?</i>	1	\$	79.00	
9	REAR VENT <i>?</i>	1	\$	502.00	
10	REAR SIDE PANEL - LH <i>new</i>	1	\$	5,559.00	
11	REAR DOOR STONE CHIP PROTECTION FILM - LH <i>X</i>	1	\$	146.00	
12	REAR WINDOW HEATED <i>new / photo</i>	1	\$	1,385.00	
13	REAR QUARTER WINDOW - LH <i>new / photo</i>	1	\$	834.00	
14	WINDOW PRIMER <i>new</i>	2	\$	47.00	
15	REAR WHEEL HOUSING LINER - LH <i>?</i>	1	\$	322.00	
16	ATTACHMENT PARTS <i>?</i>	1	\$	144.00	
17	ADHESIVE TAPES <i>new</i>	1	\$	68.00	
18	REAR BUMPER REFLECTOR - LH OUTER	1	\$	49.00	
19	REAR BUMPER REFLECTOR - LH INNER <i>X not consistent</i>	1	\$	36.00	
20	REAR PARKING AID SENSOR - INNER <i>?</i>	1	\$	299.00	
SUB TOTAL SPARE PARTS			:	\$ 14,581.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 7786 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR PARKING AID SEAL RING <i>ne/</i>	4	\$ 11.00	
22	REAR PARKING AID SENSOR - OUTER <i>?</i>	1	\$ 299.00	
23	ACRYLIC SEALANT <i>ne/</i>	S/N	\$ 180.00	
24	CAVITY WAX <i>m/</i>	S/N	\$ 140.00	
25	STONE CHIP <i>ne/</i>	S/N	\$ 180.00	
26	METAL FILLER POWDER <i>ne/</i>	S/N	\$ 280.00	
27	1/4 GLASS SEALANT <i>ne/</i>	S/N	\$ 100.00	
28	REAR WINDSCREEN SEALANT <i>ne/</i>	S/N	\$ 200.00	
29	SUNDRIES <i>?</i>		\$ 500.00	
TOTAL SPARE PARTS		:	\$ 16,471.00	
TOTAL LABOUR CHARGES		:	\$ 16,852.00	
GRAND TOTAL		:	\$ 33,323.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : **RASUL - HP 90010068**
SURVEYED DATE : **26/04/23 @ 1425**
AUTHORISED DATE : **12 days**
EXCESS COST : **TBA**
LIABILITY : **EXCESS REVERT**
REMARKS : **Resury before paint**

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 564H

Vehicle Details

Vehicle No.: SNA7786Z
Vehicle to be Exported: No
Intended Deregistration Date: 27 Apr 2023
Vehicle Make: AUDI
Vehicle Model: A6 DESIGN 2.0 TFSI (140 KW)
Primary Colour: Blue
Manufacturing Year: 2021
Engine No.: DKY015489
Chassis No.: WAUZZZF24MN071864
Maximum Power Output: 140.0 kW (187 bhp)
Open Market Value: \$41,876.00
Original Registration Date: 31 May 2021
First Registration Date: 31 May 2021
Transfer Count: 0
Actual ARF Paid: \$50,627.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 30 May 2031
PARF Rebate Amount: \$37,970.00

Intended COE Rebate Details

COE Expiry Date: 30 May 2031
COE Category: E - Open - all except motorcycle
COE Period(Years): 10
QP Paid: \$63,002.00
COE Rebate Amount: \$48,549.00
Total Rebate Amount: \$86,519.00

The information contained herein is correct as at 27 Apr 2023

OK

Audi A6 Mild Hybrid 2.0A TFSI S-tronic Design

Overview Financial Insurance Accessories Similar Research Photos

BAVARIAN
MARQUES

Price	\$194,500		
Depreciation ⓘ	\$21,120 /yr View models with similar depre	Reg Date	30-Apr-2021 (8yrs 2days COE left)
Mileage	35,000 km (17.6k /yr)	Manufactured ⓘ	2021
Road Tax ⓘ	\$1,194 /yr	Transmission	Auto
Dereg Value ⓘ	\$74,822 as of today (change)	Fuel Type	Petrol-Electric
COE ⓘ	\$46,002	OMV ⓘ	\$41,876
Engine Cap	1,984 cc	ARF ⓘ	\$50,627
Curb Weight ⓘ	1,680 kg	Power	140.0 kW (187 bhp)