

REPAIR ESTIMATE

DATE: 15.04.2023 (Sat)

INSURANCE: INCOME (LIS)

MODEL: Hyundai Ioniq

SURVEYOR: LKK-

VEHICLE NO.: SHC2234T

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Wheel Rim LH <i>set RX</i>	1		\$ 1,124.20
	SUB TOTAL			\$ 1,124.20
	LESS 20% DISCOUNTED TOTAL			\$ 899.36
	Rear Door (ZIG) Apps LH <i>Nell</i>	1		\$ 80.00
	Rear Fender (Petrol Only) LH <i>Nell</i>	1		\$ 30.00
	S/NETT SUB			\$ 110.00
	LESS 10% S/NETT TOTAL			\$ 99.00
	SPARE PARTS TOTAL			\$ 998.60
	Labour Charge			
	Panel Beating - Rear Fender Arch LH Etc			\$ 800.00 <i>700</i>
	Spray Painting Charge - Rear Bumper Etc			\$ 900.00 <i>500</i>
	TOTAL LABOUR			\$ 1,700.00
	ESTIMATE TOTAL			\$ 2,698.36

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*T = 1250
20% = 25980
= 1039.20
21050*

*248370
LIS
17/4/23
3pm
3pm*