

City Auto Pte Ltd (Co.Reg.No:199503435C)

160 Sin Ming Drive #05-01,, Sin Ming AutoCity,
Singapore 575722

Tel: 6453 1235 Fax: 6453 7944 Email: jason@cityauto.com.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2005614707-01	Date of Loss:	24/04/2023
Vehicle Reg. No.:	YR1G	Driveable?	
Driver Age/Info:	38 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	FOOD FRESH PTE LTD		
Driver:	ZENG QIANG		
Make/Model:	HINO XZU710R, 4.0 D 14FT WID CAB 5T MT (M)	Vehicle Reg. Date:	30/03/2023
Vehicle Colour:	WHITE		
Engine No:	N04CWN21012	Chassis No:	JHHUCV3F70K048022
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7 6		
Remarks:	VEHICLE IS IN		
Present Location:	CITY AUTO PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	5,575.90
Miscellaneous Items	85.00
Labour	1,770.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	7,430.90
- Excess (S\$)	700.00
(S\$)	6,730.90
+ GST 8.00% (S\$)	538.47
Nett Amount (S\$)	7,269.37

This claim is handled by: VRONICA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 26 Apr 2023)**Parts:** N/A HINO XZU710R 4.0 D 14FT WID CAB 5T MT (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** City Auto Pte Ltd/YR1G/26/04/2023 15:47**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*Front bumper	0.00	0.00	450 *250.00 F	BU
2	1		*Front bumper bracket LH	0.00	0.00	✓ *185.00 F	BT
3	1		*Front bumper bracket RH	0.00	0.00	✓ *185.00 F	BT
4	1		*Front bumper reinforcement	0.00	0.00	✓ *95.00 F	DD
5	2		*Foglamp	0.00	0.00	*440.00 F	?XNA
6	2		*Headlamp	0.00	0.00	✓ *1,100.00 F	CRA
7	1		*Front grille logo	0.00	0.00	✓ *80.00 F	MIS
8	8		*Front grille clip	0.00	0.00	✓ *16.00 F	NEC
9	1		*RH corner panel	0.00	0.00	✓ *155.00 F	MIS
10	4		*RH corner panel clip	0.00	0.00	✓ *8.00 F	NEC
11	1		*Front outer panel	0.00	0.00	✓ *320.00 F	BUK
12	1		*Front inner panel	0.00	0.00	*650.00 F	X R
13	1		*Sticker - Hino	0.00	0.00	✓ *95.00 F	NEC
14	1		*Sticker - 300	0.00	0.00	✓ *85.00 F	NEC
15	1		*Front step garnish RH	0.00	0.00	✓ *245.00 F	✓/CRA
16	1		*Front grille base	0.00	0.00	✓ *285.00 F	MIS
17	1		*Front windscreen glass moulding	0.00	0.00	✓ *195.00 F	NEC
18	1		*Front grille	0.00	0.00	✓ *680.00 F	MIS

F=Franchise part.

Sub Total (S\$)	5,069.00
+ Margin on L,N Items 10.00% (S\$)	506.90
Total Parts (S\$)	5,575.90

City Auto Pte Ltd/YR1G/26/04/2023 15:47. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	Glass sealant	40.00
2	1	License plate	20.00
3	1	License plate casing	25.00
Sub Total (\$)			85.00

NEC
MIS
CRA

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	- To remove and install front windscreen glass	New	120.00
2	To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	New	850.00
3	Spray painting on affected and replace parts	New	800.00
Gross Labour Cost (\$)			1,770.00

✓
700
600

City Auto Pte Ltd/YR1G/26/04/2023 15:47. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

- Excess = \$700k.
- Survey by Simon HS (62563561)
- P/P or L/S repair.
- Resurvey before paint for P/P repair.

Repairer, pls read.
↓↓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: