

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/LPC23004337/4203**ASSIGNMENT**From: _____
Estimated Cost: _____

Date: _____

OD / TR / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNJ8657J

at Workshop m/s _____

of _____

Insured: XC 6505K

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$40k.

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 7 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: 9384

Vehicle: IN / OUT

Veh No: SNJ8657JYr Regn: 06/12/13Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: BMWX3

c.c

1997Colour: SilverA/C: Insured / Std / NI / NASp. Reading: 76470T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: W13AWX3209001328399Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F:R:245-150 R18BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 8 mmL/Bal. 8 mmD.O.A. 26/04/23D.O.I. 27/4/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orO/S RearThe U/C Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Day 21k.Bo/ 7th. Mett 90139/5/23 2/s \$9000 indmt Allen.

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

____ \$ + RS ____ \$

Photos

Others

Report Format :

Lump Sum / I.B.I: (\$ _____)

TOTAL

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

not fullard
27/4/23
d/s 9000/
at night after my
7 days

VEHICLE No: SNJ 8657J

S.NETT ITEM

1PC	TAILGATE	1		\$2,455.00	X
1PC	TAILGATE REFLRCTOR O/S	one	428.45	\$700.00	—
1PC	TAILGATE REAR LOGO	11		\$145.00	X
1PC	TAILGATE 'X3' EMBLEM	11		\$135.00	X
1PC	TAILGATE WEATHERSTRIP	11		\$388.90	X
1PC	REAR BUMPER	DIS	1536.45	\$2,415.10	—
1PC	REAR BUMPER LOWER GARNISH	DIS	581.22	\$1,228.90	—
1PC	REAR BUMPER DIFFUSER	nn		\$820.00	X
2PCS	REAR BUMPER REFLECTORS @\$85.00	M/S 11 o/s sca		\$170.00	1PC
2PCS	REAR BUMPER SIDE RETAINERS @\$165.00	M/S 11 o/s sca	122.60	\$330.00	1PC
4PCS	REAR BUMPER PDC SENSORS @\$285.00	11		\$1,140.00	X
1PC	REAR BUMPER UNDER COVER	11		\$685.00	X
1PC	REAR BUMPER BEAM	11		\$915.00	X
1PC	REAR BUMPER SIDE BRACKET O/S	one		\$162.00	—
1PC	TAILLAMP O/S	520	612.05	\$950.00	—
1PC	TAILLAMP HOUSING PANEL O/S	1		\$900.60	X
1PC	TAILLAMP LOWER BRACKET O/S	11		\$180.00	X
1PC	REAR FENDER O/S	Body	1922.32	\$2,205.10	—
1PC	REAR FENDER INNER TRIM BOARD O/S	11		\$870.20	X
1PC	REAR FENDER OUTER PROTECTOR O/S	DIS	368.50	\$460.00	—
1PC	REAR FENDER UNDER CLOTH O/S	Torn	302.40	\$455.00	—
1PC	REAR FENDER GLASS O/S	11		\$622.30	X
1PC	REAR SHOCK ABSORBER O/S	one		\$882.00	X
1PC	REAR WHEEL HUB BEARING O/S	Daye	520.00	\$805.00	—
1PC	REAR KNUCKLE ARM O/S	work	1012.00	\$1,415.00	—
1PC	REAR LOWER ARM O/S	Surf/br	552.00	\$982.00	—
1PC	REAR TRAILING ARM O/S	twi	365.00	\$845.00	—
1PC	REAR TRUST ARM O/S	twi	280.00	\$320.00	—
1PC	REAR CONTROL ARM O/S	11		\$650.00	X
1PC	REAR CROSS MEMBER	11		\$3,220.00	X
1PC	REAR DOOR O/S	R	1820.00	\$2,201.00	X
1PC	REAR DOOR INNER RUBBER O/S	11	260.00	\$288.00	—
1SET	REAR DOOR FRAME BLACK STICKER O/S	11		\$60.00	X
1SET	REAR BUMPER CLIPS	one		\$50.00	—
1SET	REAR BUMPER UNDER COVER CLIPS	11		\$50.00	X
1SET	REAR FENDER INNER TRIM BOARD CLIPS	11		\$50.00	X
1SET	REAR TYRE O/S	put	19250	\$380.00	60% 1505/11
1PC	REAR SPORT RIM O/S 18 INCH	work/br		\$1,200.00	60% 1505/11
				\$31,731.10	

52

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REPLACED REAR PDC SENSOR	\$80.00	50
TO DISMANTLE & REFIX REAR WINDSCREEN	\$150.00	X
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	80
TO DISMANTLE & REFIX REAR FENDER GLASS	\$100.00	80
TO TRANSFER TAILGATE MECHANISM	\$100.00	X
TO SPRAY PROOFING	\$180.00	40
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE	\$450.00	150
TO CONDUCT WHEEL ALIGNMENT	\$150.00	100
TO DIAGNOSTIC & REPROGRAMME SYSTEM	\$380.00	80
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$2,000.00	800
TO PUTTY & SPRAY PAINTING	\$2,000.00	1000
TOTAL	\$37,491.10	

2400

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 8899.99
52
8454.99
750
2400
11604.99
9283