Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Alfred Toh Date: 28 Apr 2023

Preliminary Advice

Vehicle No : SFV5055Y Accident Date : 21/04/2023

Make : SUBARU FORESTER Policy No.

DMPCSNW00248932201

Assignment Date : 27/04/2023 Excess : S\$1,000.00

Date of Inspection : 27/04/2023 Est. Duration of Repair : 9

Inspection At : WAH HONG MOTORS & CREDIT PTE LTD (HQ)

38 TOH GUAN ROAD EAST, #01-57, ENTERPRISE HUB

SINGAPORE 608581

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,137.21
Revised Amount	:S\$	8,985.21
Check Items (Estimated)	:S\$	1,974.00
Total	:S\$	10,959.21

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
-------------------	------

Pre-Accident Value :S\$ 66,000.00
COE / PARF Rebate :S\$ 31,221.00
Salvage Value :S\$

Margin for Repair :S\$ 34,779.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly	/
	let us have your authorisation.	

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.