

OTORIMAGE ENTERPRISES PTE. LTD.
5 LENG KEE ROAD
INGAPORE 159097

STIMATE : ACCIDENT/BODY REPAIRS
ORKSHOP : LENG KEE
ONTACT NO :
EFERENCE : INS/IC/CHI/0113/2023
ATE : 25-APR-2023

HINA TAIPING INSURANCE (SINGAPORE)PTE LTD
ANSON ROAD
15-00 SPRINGLEAF TOWER
INGAPORE S(079909)
EL : 6389 6111
AX : 6222 1033

WNER'S NAME : TAN WEE HENG, DAVID (CHEN WEIXING, DAVID)
DDRESS : 195 JALAN LOYANG BESAR
#04-02
S(509439)
ELEPHONE NO : 9742 4712

YPE OF CLAIM : THIRD PARTY CLAIM
OLICY NO : 7210012318-02 AIG
EHICLE NO : SGD7172L
ODEL/YEAR : FORESTER 2.0I-L AWD CVT
NGINE NO : FB20YE25071
HASSIS NO : JF1SJ5KC5JG111372
ILEAGE : 1 KM
ATE IN : 25/04/2023
IABILITY : 0.00
XCESS CLAUSE : 0.00
STIMATE BY : DENNIS LEONG JIA HUI
CCIDENT DATE : 25/04/2023

rint Date : 25/04/2023
rint Time : 16:47:20

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SGD7172L

NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST CHINA TAIPING-SGD7172L		
2	ZZ/001	DOA:24/APR/2023 TIME:0830 HRS LOCATION:BAYFRONT AVE		
3	ZZ/002	REPLACE FRONT BUMPER,ENERGY ABSORBER,BUMPER BEAM AND FRT GRILLE	3500.00	600
4	ZZ/003	REPLACE REAR BUMPER,BUMPER BEAM,END PANEL,SPARE TYRE FLOOR & TAILGATE	3500.00	3000
5	ZZ/004	RESPRAY FRONT BUMPER & BUMPER BEAM	1600.00	600
6	ZZ/005	RESPRAY REAR BUMPER,BUMPER BEAM,END PANEL,SPARE TYRE FLOOR & TAILGATE	3500.00	2500 2500
7	ZZ/006	TRANSFER REVERSE SENSOR (OLD TO NEW BUMPER)	100.00	80
8	ZZ/007	TRANSFER TAILGATE MECHANISM	150.00	
9	ZZ/008	INSTALL REAR WINDSCREEN	300.00	
10	ZZ/009	TO SUPPLY & INSTALL REAR WINDSCREEN SOLAR FILM	145.00	invoice
11	ZZ/011	TO CONDUCT WATER SEEPAGE TEST	100.00	30
12	ZZ/012	REMOVE & REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIR	150.00	80
13	ZZ/013	TO SUPPLY & INSTALL FRONT SENSOR - 2EYES	300.00	780
14	ZZ/014	TO INSTALL REAR CARGO STEP PANEL	100.00	60
15	ZZ/015	INSTALL FRONT & REAR UNDER SPOILER	250.00	
16	ZZ/016	FAULT DIAGNOSTIC (RESET)	280.00	
17	ZZ/017	SUNDRIES	100.00	20
18	ZZ/10	REMOVE & REFIX EXHAUST SYSTEM	150.00	?
TOTAL LABOUR CHARGES			14225.00	

TORIMAGE ENTERPRISES PTE. LTD.
5 LENG KEE ROAD
SINGAPORE 159097

ATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGD7172L

/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
1 EXH PIPE ASSY R <i>? bt/</i>	44200SG080			765.90 ✓	
2 MUFFLER ASSY RH NA <i>? bt/</i>	44300SG010			617.90 ✓	
3 FLOOR PAN R R CP <i>repair</i>	52129SG0019P			444.00	
4 SKIRT COMPL REAR END PANEL <i>bt/</i>	52401SG0109P			296.00 ✓	
5 BUMPER FACE REAR FORESTER IL <i>cm/</i>	57704SG012			610.50 ✓	
6 BRKT CORNER F RH <i>X n</i>	57707SG000			37.00	
7 BRKT CORNER F LH <i>X n</i>	57707SG010			37.00	
8 BRKT SD F RH <i>X n</i>	57707SG020			13.00	
9 BRKT SD F LH <i>X n</i>	57707SG030			13.00	
10 BRKT SD R RH <i>ne/</i>	57707SG080			14.80 ✓	
11 BRKT SD R LH <i>ne/</i>	57707SG090			14.80 ✓	
12 BUMPER FRT (FOR HL/W) <i>de/</i>	57709SG011			610.50 ✓	
13 BACK BEAM CPL F <i>X n</i>	57711SG0009P			296.00	
14 BEAM <i>BT Beam compl R Eu</i>				296.00	
15 ENERGY ABSOR F <i>bt/</i>	57722SG020			129.50 ✓	
16 COVER HOOK R <i>X n</i>	57731SG010EN			13.00	
17 COVER BMPR R (EXHAUST) <i>X n</i>	57731SG060			14.80	
18 COVER HOOK F SP <i>X n</i>	57731SG070			5.55	
19 PANEL CPL R/G NA <i>bt/</i>	60809SG0109P			1102.60 ✓	
20 GLASS R/G <i>new photo/</i>	63019SG000			821.40 ✓	
21 RUBBER DAM GLS <i>ne/</i>	63232SG000			7.40 ✓	
22 RUBBER R/G <i>ne/</i>	63232SG010			13.00 ✓	
23 WSTR DR R G <i>X n</i>	63516SG001			111.60	
24 CLIP BMPR *9 PCS <i>ne/</i>	909140007			21.60 ✓	
25 CLIP *2 PCS <i>ne/</i>	909140062			6.00 ✓	

TORIMAGE ENTERPRISES PTE. LTD.
LENG KEE ROAD
NGAPORE 159097

		DAMAGED PARTS & PRICES			
/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT S/LIST REMARKS
26	LETTER MK R IMPS/SPORT <i>nee✓</i>	FORESTER *SPORT* 93079FJ020			72.00 ✓
27	LETTER MARK FORESTOR R <i>nee✓</i>	93079SG000			40.70 ✓
28	LETTER MK R SUB <i>nee✓</i>	93079SG030			66.60 ✓
29	CARGO STEP PANEL S/S <i>de✓</i>	E7710SG000			460.00 ✓
30	FRONT GRILLE <i>X n n</i>	J1010SG101			1200.00
31	FORESTER 2.0I-S KIT FRONT UNDER SPOILER (TCS) <i>for✓</i>	TCS-FJ8-FL-002			1398.00 ✓
32	FORESTER 2.0I-S KIT REAR UNDER SPOILER (TCS) <i>ca✓</i>	TCS-FJ8-RL-002			1702.00 ✓
33	FRONT NUMBER PLATE <i>St✓</i>	WM001			45.00 ✓
SUB TOTAL			0.00	0.00	11297.15 0.00
LESS DISCOUNT ()			0.00	0.00	0.00 0.00
GRAND TOTAL			0.00	0.00	11297.15 0.00
OVERALL TOTAL			11297.15		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SGD7172L

TOTAL LABOUR CHARGES	14225.00
TOTAL SPARE PARTS CHARGES	11297.15
GRAND TOTAL	25522.15 *

* All charges do not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

Rasul - Hp 92021568
02/05/23 @ 1100
9 days
Repair before paint

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

117.8
25639.95

DISCLAIMER NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SG07172L

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
1	GASKET <i>suppl new</i>	44011SG000			7.40	OK
2	EXH PIPE ASSY R	44200SG080			765.90	OK
3	MUFFLER ASSY RH NA	44300SG010			617.90	OK
4	R EXH CUTTER RH/LH <i>suppl U</i>	44370FG002			74.00	OK
5	FLOOR PAN R R CP	52129SG0019P			444.00	X
6	SKIRT COMPL REAR END PANEL	52401SG0109P			296.00	OK
7	BUMPER FACE REAR FORESTER IL	57704SG012			610.50	OK
8	BRKT CORNER F RH	57707SG000			37.00	X
9	BRKT CORNER F LH	57707SG010			37.00	X
10	BRKT SD F RH	57707SG020			13.00	X
11	BRKT SD F LH	57707SG030			13.00	X
12	BRKT SD R RH	57707SG080			14.80	OK
13	BRKT SD R LH	57707SG090			14.80	OK
14	BUMPER FRT (FOR HL/W)	57709SG011			610.50	OK
15	BACK BEAM CPL F	57711SG0009P			296.00	X
16	BEAM COMPL R EU	57711SG0219P			296.00	OK
17	ENERGY ABSOR F	57722SG020			129.50	OK
18	COVER HOOK R	57731SG010EN			13.00	X
19	COVER BMPR R (EXHAUST)	57731SG060			14.80	X
20	COVER HOOK F SP	57731SG070			5.55	X
21	PANEL CPL R/G NA	60809SG0109P			1102.60	OK
22	GLASS R/G	63019SG000			821.40	OK
23	RUBBER DAM GLS	63232SG000			7.40	OK
24	RUBBER R/G	63232SG010			13.00	OK
25	WSTR DR R G	63516SG001			111.60	X

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGD7172L

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
26	REFLEC AY RH <i>Suppl cm ✓</i>	84281SC000			20.40	OK
27	BOLT SP TIRE HLD RM8 <i>Suppl nec ✓</i>	901720002			10.40	OK
28	CLIP BMR *9 PCS	909140007			21.60	OK
29	CLIP *2 PCS	909140062			6.00 ✓	OK
30	LETTER MK R IMPS/SPORT FORESTER *SPORT*	93079FJ020			72.00 ✓	OK
31	LETTER MARK FORESTOR R	93079SG000			40.70 ✓	OK
32	LETTER MK R SUB	93079SG030			66.60 ✓	OK
33	SUPPORTER HOLDER <i>Suppl nec ✓</i>	97047FG000			5.60	OK
34	CARGO STEP PANEL S/S	E7710SG000			460.00 ✓	OK
35	FRONT GRILLE	J1010SG101			1200.00	X
36	FORESTER 2.0I-S KIT FRONT UNDER SPOILER (TCS)	TCS-FJ8-FL-002			1398.00 ✓	OK
37	FORESTER 2.0I-S KIT REAR UNDER SPOILER (TCS)	TCS-FJ8-RL-002			1702.00 ✓	OK
38	FRONT NUMBER PLATE	WM001			45.00 ✓	OK
SUB TOTAL			0.00	0.00	9230.00	0.00
LESS DISCOUNT ()			0.00	0.00	0.00	0.00
GRAND TOTAL			0.00	0.00	9230.00	0.00
OVERALL TOTAL			9230.00			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SGD7172L

NETT ITEM	0.00
LESS 20 %	0.00
NETT AMOUNT	0.00
LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00
SPECIAL NETT AMOUNT	9230.00
S/LIST ITEM	0.00
LESS 30 %	0.00
S/LIST AMOUNT	0.00
TOTAL LABOUR CHARGES	8325.00
TOTAL SPARE PARTS CHARGES	9230.00

TOTAL CHARGES	17555.00
ADD 8 % GST	1404.40

GRAND TOTAL	18959.40
