



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23004347/Wwy3e2 Date: 09/06/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMG 8977M	Veh. Inspected	SNE 9444B	
Policy No.		Coverage (\$)	0.00	
Claim No.	IVS23/0786	Excess (\$)	0.00	
Assign From	ANDY SEAH	Assign Date	27/04/2023	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COROLLA ALTIS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	MR2BZ3BE600008847	Colour	SILVER	
Odometer	94997 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	SAILUN	6 mm	
L/H Front Tyre	225/45 R17	SAILUN	6 mm	
R/H Rear Tyre	225/45 R17	DUNLOP	6 mm	
L/H Rear Tyre	225/45 R17	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/04/2023	Inspection Date	27/04/2023	
Survey held at	MY CAR CONSULTANT PTE LTD 60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869			
5a. Remarks				
A)REGISTRATION DATE: 22 APR 2022 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	