

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422 / 6745 4422 Fax : 6747- 6720 REG NO 200501102H

Auto & General Insurance (Singapore) Pte. Ltd
trading as Budget Direct Insurance
190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore 239924
Tel: 6221 2199

Quotation
DATE : 27.04.2023
VEH NO : SKA5760X
MODEL : Hyundai i30
D O A : 25.04.2023
YR REF : SMU6027U

Veron.

KMHDC5IDMAU258657

Attn : Motor Claim Dept (Pls arrange vehicle surveyor & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SKA5760X (HYUNDAI I30)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
-------------	--------------------	------------	------------

NO LIST ITEMS

1	Rear Number Plate Lamp <i>new</i>	2	116.40 <i>x</i>
2	Rear Bumper <i>dent</i>	1	496.20 <i>✓</i>
3	Rear Bumper Side Holder - LH & RH <i>dent</i>	2	70.80 <i>✓</i>
4	Rear Bumper Reinforcement <i>crack</i>	1	296.40 <i>✓</i>
5	Rear Bumper Reinforcement Stay <i>dent</i>	2	168.80 <i>✓</i>
6	Rear Bumper Bracket <i>dent</i>	5	90.00 <i>✓</i>
7	Rear Bumper Undercover <i>bum</i>	1	286.50 <i>✓</i>
8	Rear End Panel <i>dent</i>	1	499.30 <i>✓</i>
9	Rear End Panel Top Garnish <i>dent</i>	1	96.20 <i>✓</i>
10	Taillamp - LH & RH <i>crack</i>	2	936.40 <i>✓</i>
11	Taillamp Panel - LH & RH <i>dent</i>	2	493.60 <i>x</i>
12	Tailgate <i>dent</i>	1	1,501.40 <i>✓</i>
13	Tailgate Lock <i>dent</i>	1	166.80 <i>✓</i>
14	Tailgate Weatherstripe <i>cut</i>	1	167.40 <i>✓</i>
15	Tailgate Inner Trimboard <i>new</i>	1	286.50 <i>x</i>
16	Tailgate Damper <i>new</i>	2	324.80 <i>x</i>
17	Tailgate Glass Moulding <i>new</i>	1	122.40 <i>✓</i>
18	Hyundai Logo <i>new</i>	1	50.40 <i>x</i>
19	Hyundai Wording <i>new</i>	1	48.10 <i>✓</i>
20	i30 Wording <i>new</i>	1	46.90 <i>✓</i>
21	Rear Fender Inner Trimboard - LH & RH <i>RH bum</i>	2	482.40 <i>241.20</i>
22	Spare Tyre Panel <i>bracket</i>	1	776.20 <i>✓</i>
23	Spare Tyre Panel Top Board <i>new</i>	1	282.30 <i>x</i>
24	Rear Exhaust Pipe <i>3 up</i>	1	726.90 <i>x</i>
25	Rear Exhaust Pipe Mounting <i>new</i>	1	36.40 <i>x</i>
26	Rear Exhaust Gasket	1	31.60 <i>x</i>
			<hr/> \$ 8,601.10

6011
4808.80

RE : ESTIMATE FOR ACCIDENT REPAIR SKA5760X (HYUNDAI I30)

Less 20% (1,720.22)
 \$ 6,880.88

S/NET ITEMS

1	Rear Number Plate <i>Best</i>	1	30.00 ✓
2	Rear Number Plate Holder <i>shhd</i>	1	30.00 ✓
3	Rear Bumper Clips <i>mu</i>	1 set	30.00 ✓
4	Rear Bumper Undercover Clips <i>mu</i>	1 set	30.00 ✓
5	Reverse Sensor <i>dup</i>	1 set	280.00 <i>200</i>
6	Rear End Panel Top Garnish Clips <i>mu</i>	1 set	20.00 ✓
7	Rear End Panel Sealant <i>mu</i>	1	60.00 ✓
8	Tailgate Inner Trimboard Clips <i>mu</i>	1 set	30.00 X
9	Tailgate Glass Sealant <i>mu</i>	1	60.00 ✓
10	Advertisement Sticker <i>mu</i>	1	300.00 <i>200</i>
11	Rear Fender Inner Trimboard Clips <i>mu</i>	2 sets	60.00 <i>30</i>
12	Spare Tyre Panel Sealant <i>mu</i>	1	60.00 ✓

Total Parts \$ 7,870.88

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$ 1,600.00 <i>1300</i>
2	To putty & spray up paint works	\$ 1,400.00 <i>1800</i>
3	To check wiring	\$ 50.00 <i>30</i>
4	To remove reverse sensor	\$ 100.00 <i>50</i>
5	To apply tuff coat	\$ 150.00 <i>100</i>
6	To remove upholstery & rear seat	\$ 350.00 <i>180</i>
7	To remove tailgate glass	\$ 180.00 <i>120</i>
8	To transfer tailgate fittings	\$ 150.00 <i>80</i>
9	To remove exhaust pipe	\$ 150.00 <i>X</i>

Total Labour \$ 4,130.00

Grand Total **\$ 12,000.88**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices **GST Will be reflected in the final bills**
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

NOTE :

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN

Acknowledged by Repairer
 Signature:
 Date:

total: 8418.80
L/S: 67K
09 Days