

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Cecilia Lee

Date: 27 Apr 2023

Preliminary Advice

Vehicle No	: SKM7128X	Accident Date	: 20/04/2023
Make	: BMW 520I	Policy No.	: DMPCSNW0055702302
Assignment Date	: 27/04/2023	Excess	: S\$750.00
Date of Inspection	: 27/4/2023	Est. Duration of Repair	:
Inspection At	: LAI HUAT (MENG KEE) MOTOR PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	Total Loss
Revised Amount	:S\$	Total Loss
Check Items (Estimated)	:S\$	0.00
Total	:S\$	
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	46,000.00
COE / PARF Rebate	:S\$	34,569.00
Salvage Value	:S\$	
Margin for Repair	:S\$	11,431.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :