

TG Auto Pte Ltd
8 Kaki Bukit Ave 4 #03-34
Singapore 415875
david@tgauto.com.sg
GST Registration No. :
201536439H



Quotation

ADDRESS

Navas SJH9999Z

QUOTATION NO. TG2211-001

DATE 08/11/2022

REGISTRATION PLATE

SJH9999Z

CAR MODEL

BMW 535

ACTIVITY	QTY	RATE	AMOUNT
Replacement of Rear Bumper Bracket	1	250.00	250.00
Replacement of Rear Bumper	1	1,200.00	1,200.00
Rear Bumper Respray	1	450.00	450.00
Labour to Install	1	200.00	200.00

SUBTOTAL	2,100.00
GST TOTAL	147.00
TOTAL	S\$2,247.00

Accepted By

Accepted Date