

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI23004368/SVY3E2
Date: 20/06/2023**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MK000353
Claimant Vehicle No :	SHD3748R	Insured Vehicle No :	GBJ5510K
Date of Loss:	26/04/2023	Nature of Claim:	TP
		Claim No:	M2302706

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD3748R	Engine No:	2ZRS065838
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Chassis No:	JTDKB3FU403563789
Reg. Date:	30/08/2017 (Man. Year: 2017)	Odometer:	747337 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	3,927.05	3,049.61	877.44	22.34	
Miscellaneous Items	11.00	11.00	0.00	0.00	
Labour	2,330.00	1,580.00	750.00	32.19	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	6,268.05	4,640.61	1,627.44	25.96	
Approved Total (Overridden) (S\$)		3,700.00			
	(S\$)	6,268.05	3,700.00	2,568.05	40.97
+ GST 8.00/8.00% (S\$)	501.44	296.00	205.44	40.97	
Nett Amount (S\$)	6,769.49	3,996.00	2,773.49	40.97	

INSPECTION

Date of Assignment:	27/04/2023	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang) ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	28/04/2023	Inspected At:	59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 20 Jun 2023)
Parts: 144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHD3748R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Deformed	503.04 FL	*503.04 FL
2	1		*REAR BUMPER BEAM	Not Necessary	378.32 FL	*- FL
3	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
4	1		*REAR BUMPER TOW COVER	Missing	82.70 FL	*82.70 FL
5	1		*REAR BUMPER CENTRE MOULDING	Cracked	654.96 FL	*654.96 FL
6	1		*TAILLAMP ASSY UPPER RH	Cracked	557.90 FL	*557.90 FL
7	1		*TAILLAMP ASSY LOWER RH	Not Necessary	548.40 FL	*- FL
8	1		*REAR BUMPER SIDE BRACKET RH	Not Necessary	94.80 FL	*- FL
9	1		*REAR WINDSCREEN GLASS LOWER	Cracked	805.80 FL	*805.80 FL
10	1		*SEAL REAR BUMPER SIDE RH	Not Necessary	148.40 FL	*- FL
11	1		*BOOTLID EMBLEM - PRIUS	Necessary	62.14 FL	*62.14 FL
12	1		*BOOTLID EMBLEM - HYBRID	Necessary	62.14 FL	*62.14 FL
13	1		*BOOTLID EMBLEM - TOYOTA STAR	Necessary	81.43 FL	*81.43 FL
14	1		*GARNISH ASSY BACK DOOR OUTSIDE	Scratched	1,054.71 FL	*1,054.71 FL
15	1		*BOOTLID COMFORT LOGO	Necessary	30.00 F	*30.00 F
16	1		*BOOTLID COMFORT TEL.NO LOGO	Necessary	30.00 F	*30.00 F
17	1		*BOOTLID APPS LOGO	Necessary	40.00 F	*40.00 F
18	2		*WINDSCREEN SEALANT	Necessary	46.00 FL	*46.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	5,202.74	4,032.82
- List Item Discount on L Items 25.00/25.00% (S\$)	1,275.69	983.21
Total Parts (S\$)	3,927.05	3,049.61

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
			Sub Total (\$)	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	700.00
2	SPRAYPAINT	New	800.00	700.00
3	CHECK WIRING	New	50.00	30.00
4	TUFF KOTE	New	50.00	0.00
5	REMOVE/ REFIX REAR WINDSCREEN GLASS	New	120.00	60.00
6	REMOVE/REFIX REVERSE SENSOR	New	50.00	30.00
7	TOWING FEE	New	60.00	60.00
			Gross Labour Cost (\$)	2,330.00
				1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >