


ASS. REG. BY:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD/TP/WS/TP RES/OD RES/EVA/INV/MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: FBQ 6199H INC
 Policy No. _____
 Claims No. MT/1219751-002
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Valt: _____

Veh No: Sh9960C Yr Regt: 30/10/2019
 Type: MCar / M.Cycle / Bus / Van / Lorry / ~~Tr~~ / Prime Mover L
 Truck / Trailer or _____
 Make: Hyundai Ionix CC 1.580
 Colour: Blue AC: Insured / ~~Std~~ / ~~HTA~~
 Sp. Reading: 568719 Y/Radio: Insured / ~~Std~~ / ~~NI~~ / ~~NA~~
 Eng No: _____
 C/Nr: Kmh c8510110188594
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Mod: NI / S/Rim / STD / R/Rim or _____
 Tyre Size: F: 195/65 R15
 R: 195/65 R15

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: \$ _____
 IDAC Accident Report: _____ Consider: Yes or No
 GIA / PR Scant: _____ Consider: Yes or No
 Est. Repair: 3 days Rate: Yes or No
 Lump Sum: 20 % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN/OUT



BS/DUN/EXNOVA/GY/FS/LZA/MC/OHTSU/PR/SUM/
 TOYO/YOKO or WBS7/OKK
 Front: _____ Rear: _____
 R/Bal: 5 mm R/Bal: 5 mm
 L/Bal: 5 mm L/Bal: 5 mm
 D.O.A: 12/4/23 D.O.L: 13/4/23
 Survey held at: Comfort
 Des. of Damages: Fnt / Rear / O/S / AUS / UIC / Roof top or _____

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
30/4/23	Irfan confirmed LS \$850 (Red 349.25, 29%)
	Balance:
	yearly:
	mv:
	nu:

Date/Time, File Pass to? ☐ : Prel. Report
☐ : Final Report
 1) _____
 Date/Time, File Return to? _____
 2) 11/5/23-typist
 Report Format: TP
 Lump Sum H.B.J: (\$ 850)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

B + RS: \$ _____

Photos: _____

Others: _____

TOTAL: _____

Date/Time: 13.04.2023 08:19

Page : 1

Job: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 5892869

JC NO305551023

OWNER MS COMFORT TRANSPORTATION PTE LTD TOMER NO 7010045 RESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (R) (P) (O)	REGN NO: SH 9960C	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL IONIQ(G3)	DATE/TIME IN 12.04.2023 15:45
	YR OF MANU. 30.10.2019	TARGET DATE
	CHASSIS CODE KMHC851CVLU188594	COMPLETION DATE/TIME:

COUNT CARD NO.

dent Date: 12.04.2023
RE: 3P 12.04.2023/C


JOB DESCRIPTION

LS
Income

PBQ
6199H

10 LABOR CODE
PB

DESCRIPTION
LUMP SUM REPAIR-SH 9960C-TP



CKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Adgement Slip

Exit Pass

No.: SH 9960C LIMITS

Vehicle No.: SH 9960C

if Service Advisor

Signature/Date

Name of Service Advisor

Date

eturned to Service Reception upon collection

To be kept by Security Guard