

REPAIR ESTIMATE

FBQ 6199 H

DATE: 13.04.2023INSURANCE: INCOMEMODEL: Hyundai IoniqSURVEYOR: LKK-VEHICLE NO.: SH 9960CMVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Door LH <i>part</i> BE <i>Outer moulding</i>	1		\$ 125.30
				\$ 125.30
				\$ 25.06
	SUB TOTAL			\$ 100.25
	LESS 20%			
	DISCOUNTED TOTAL			
	Rear Door (ZIG) Apps LH <i>NCC</i>	1		\$ 80.00
	Rear Fender (Petrol Only) LH <i>vec</i>	1		\$ 30.00
				\$ 110.00
	S/NETT SUB			\$ 11.00
	LESS 10%			\$ 99.00
	S/NETT TOTAL			
	SPARE PARTS TOTAL			\$ 199.25
	<u>Labour Charge</u>			
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 600.00
	TOTAL LABOUR			\$ 1,000.00
	ESTIMATE TOTAL			\$ 1,199.25

350
500

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

1049.25
210 = 209.85
= 839.40
= 850

3 days

45

1314123

S/irm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: