

CITYCAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC 3872

DATE 15.04.2023

MAKE REG.22.03.2023

MODEL PRIUS G4A

CHIANG/INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRT DOOR SIDE MIRROR ASSY RH <i>orig</i>			\$1,728.70 ✓
1	FRT DOOR SIDE MIRROR RH <i>missing</i>			\$141.90 ✓
	SUB TOTAL			\$1,870.60
	LESS 25%			\$467.65
	DISCOUNTED TOTAL			\$1,402.95
	Labour Charge			\$120.00 100
	Panel Beating			\$120.00 100
	Spray Painting Charge			\$240.00
	TOTAL LABOUR			\$1,642.95
	ESTIMATE TOTAL			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

1 days T=162.95

P/P

17/4/23

2pm

10km

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: