

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (After Sales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E**19 APR 2023**

Estimate No. : b1 65708	Page No. : 1 of 5
Date Estimated : 19/04/2023	
Prepared By : Chua Kee Sin	91165600

- ESTIMATE REPAIR FOR - Chow Kong Keong 9 Serangoon Ave 2 #10-24 Singapore 556134	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMS8373S	WBAJA12020WW35462	31/10/2019	5201	50404

DESCRIPTION	VALUE
Replace rear bumper include remove attachment etc	850 1,275.00
Painting rear bumper	934 1,038.00
To check electrical wiring system and lighting at the rear section for proper function.	168 177.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	168 177.00
To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x).	NN X 531.00
To replace tyre and wheel rim including balancing. (1x). right rear	NN X 94.00
Sundries.	? 150.00
Total Labour 1:	3,442.00

DESCRIPTION	QTY	PRIC	VALUE
ALLOY RIM 8JX18 DOUBLE SPK 634	1	1,207.35	NN 1,207.35
HUB CAP WITH CHROME EDGE	1	32.25	NN 32.25
(S/L) LH PROTECTION FOIL	1	14.15	? 14.15
(S/L) RH PROTECTION FOIL	1	14.15	? 14.15
REAR BUMPER RH SIDE GUIDE	1	179.90	DIS 179.90
REAR BUMPER TRIM STRIP	1	119.40	? 119.40
REAR BUMPER PANEL PRIMED (PDC/PMA)	1	1,664.50	CUT 1,664.50
SET MOUNTING PMA SENSOR	1	73.75	NEG 73.75
(S/L) CLIP	2	5.50	NEG 11.00
Total Parts :			3,316.45

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 65708
Date Estimated : 19/04/2023
Prepared By : Chua Kee Sin

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMS83738	WBAJA12020WW35462	31/10/2019	5201	50404

- Not Authorized
- Excess = \$600/2
- Resurvey before painting
- Survey by Simon (62563561)
- 3 days to repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	3,442.00
Parts	:	3,316.45
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 8%	:	540.68
Grand Total	:	7,299.13

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **