

Taught

cc/SMR23004388/Tg.43

COE 2024 out

Veh No: 537 5976D Yr Regn: 2007 10st

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Plymouth Arrow* . . . C.C. *1591*

Colour Green A/C: Insured / Std / NI / NA

Sp. Reading 221501 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KMH09415M#9871185

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or /

N/S	O/S

Tyre Size: F: 195/65R15

R: 1-1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO of *Nexen*

Front Rear

R/Bal.	6	mm	R/Bal.	6	mm
--------	---	----	--------	---	----

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 8/5/25

Vehicle: IN / OUT

Survey held at Hokwang

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

[illegible]

☐: Preli. Report

☐: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Feet:

Transportation:

Photos

Others

Penetration :

Lump Sum / L.E.A. (Y)

Add Fee: : Site Insp (\$

I: Interview (\$)

Tech. Invs (\$

Weekend (\$

TOTAL

Kok Wang Car Grooming
1 Soon Lee Street #06-40 Pioneer Centre
Singapore 627605
Hp: 91839633 E-mail: vianong@gmail.com

ESTIMATE REPORT

Vehicle Number : SJT5476D
 Make And Model : Hyundai Avante
 Date of Accident : 21 April 2023

S/No	Parts	QTY	Unit Price	List Price
1	Rear bumper	1		\$ 515.00 <i>de</i>
2	Rear bumper side retainer LH & RH	2	\$ 34.00	\$ <i>RH x 2</i> 68.00 <i>LH x 2</i>
3	Rear bumper inner upper bracket	2	\$ 20.00	\$ <i>RH x 2</i> 40.00 <i>LH x 2</i>
4	Rear bumper inner lower bracket	3	\$ 20.00	\$ 60.00 <i>x 3</i>
5	Rear bumper reinforcement	1		\$ 295.00 <i>cut</i>
6	Rear bumper reinforcement bracket LH & RH	2	\$ 79.00	\$ <i>RH x 2</i> 158.00 <i>LH x 2</i>
7	Rear bumper inner sponge	1		\$ 135.00 <i>cut</i>
8	Rear end panel	1		\$ 581.00 <i>cut</i>
9	Rear end panel top garnish	1		\$ 65.00 <i>x 2</i>
10	Rear bootlid	1		\$ 985.00 <i>cut</i>
11	Rear bootlid hinge LH & RH	2	\$ 132.00	\$ 264.00 <i>x 2</i>
12	Rear bootlid lamp LH & RH	2	\$ 169.00	\$ 338.00 <i>LH cut</i>
13	Rear bootlid 'LOGO' emblem	1		\$ 25.00 <i>cut</i>
14	Rear bootlid 'AVANTE' emblem	1		\$ 41.00 <i>cut</i>
15	Rear bootlid 'S' emblem	1		\$ 25.00 <i>cut</i>
16	Rear bootlid inner trimboard	1		\$ 151.00 <i>x 2</i>
17	Rear bootlid lock	1		\$ 119.50 <i>cut</i>
18	Rear bootlid weatherstrip	1		\$ <i>un</i> 83.40 <i>cut</i>
19	Rear taillamp LH & RH	2	\$ 314.00	\$ <i>RH x 2</i> 628.00 <i>LH cut</i>
				\$ 4,576.90
Less 20%				\$ 915.38
Total				\$ 3,661.52

Special Nett Item

1	Rear bumper clips	1 set	\$	60.00	3 one ✓
2	Rear end panel top garnish clips	1 set	\$	40.00	x 1 ✓
3	Rear bootlid inner trim clips	1 set	\$	60.00	x 2 ✓
4	Panel sealant	2 tube	\$	100.00	x 1 ✓
5	Reverse sensor	1 set	\$	300.00	200 x 2 ✓
Total			\$	560.00	

Labour & Misc Charges

To dismantle, replace & panel beating affected parts for rear portion.	\$ 1,200.00 <i>600</i>
To spray paint on affected areas for rear portion.	\$ 1,200.00 <i>600</i>
To remove/replace/refit rear upholstery etc.	\$ 200.00 <i>60</i>
To remove/replace/refit rear bootlid components.	\$ 120.00 <i>60</i>

To remove/replace/refit reverse sensors.
To apply anti-rust on affected areas.
To check wiring.

\$	100.00	30
\$	100.00	30
\$	50.00	30

Total	\$	2,970.00
--------------	-----------	-----------------

Grand Total :	\$	7,191.52
----------------------	-----------	-----------------

Tanplin 97495749 / 62565501
wp 8/5/23 2 3pm
L/S Resurvey after repair
tanplin @ 11hant.w
05 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SN08234P0004 National Assessment Centre Services (159721)
 ENTRY DATE & TIME: 25/04/2023 14:47 (SGT)
 SUBMITTED BY: Roal Bin Abdul Waheb
 VERSION: 1 (25/04/2023 14:47 (SGT))

Your NCD will be affected due to late reporting

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	25/04/2023 14:47 (SGT)
Reported by	Actual Driver
Date of Accident	21/04/2023 13:56 (SGT)
Exact Location of Accident	Braddell Rd, Singapore
Additional Location Information	EXIT 10 (TOWARDS PIE CHANGI AIRPORT)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number: SJT5476D

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	UDRIVE AUTOMOBILE
Company Reg No	53398901L
Email Address	maxber1999@yahoo.com
Mobile Phone No	(Phone) +65-88288428
Alternative Phone No	

VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	Avanto
Variant	
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1591

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte Ltd
Policy Number / Cover Note Number	DMHC SNW00019962200

DRIVER

Name of Driver	LEE CHOON HOU
NRIC No	S7615753G
Date Of Birth	28/05/1976
Occupation	Outdoor

 Accident report SN08234P0004

Page 1 of 13

Date Of Driving Pass	10/03/2003
Driving experience	20 YEARS AND 1 MONTH
Gender	Male
Mobile Number	(Phone) +65-90686916
Alt. Phone Number	.
Email Address	maxber1999@yahoo.com
Address	BLK 554 ANG MO KIO AVENUE 10 #03-2036
Address complement	.
Postcode	560554
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Holder
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	.
Insurance Company of Other Vehicle Owned by Driver	.

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	.
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	.
Translator's ID	.
Translator's phone number	.
Translator's email	.
Original language used in the statement	.

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	.

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD6338X
Vehicle Manufacturer	.
Vehicle Model	.
Vehicle Variant	.
Vehicle Colour	.
Vehicle Category	Taxi
Name of Driver	.
Contact Number	.

Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

DECLARATION

IMPORTANT NOTICE

1. This document is a copy of the original document and is not to be used for any other purpose.
 2. This document is a copy of the original document and is not to be used for any other purpose.
 3. This document is a copy of the original document and is not to be used for any other purpose.
 4. This document is a copy of the original document and is not to be used for any other purpose.
 5. This document is a copy of the original document and is not to be used for any other purpose.
 6. This document is a copy of the original document and is not to be used for any other purpose.
 7. This document is a copy of the original document and is not to be used for any other purpose.
 8. This document is a copy of the original document and is not to be used for any other purpose.
 9. This document is a copy of the original document and is not to be used for any other purpose.
 10. This document is a copy of the original document and is not to be used for any other purpose.

PIE
Towards Chong Chong



Andrew

A) 29 58910
B) 310 61882

Chong Chong

Chong Chong
PIE
Towards Chong Chong

Bradell Road
Exit 10



CS CamScanner

SKETCH PLAN #2

Describe Circumstances of the Accident

On 21 April 2023, I was driving toward PIF (Toward Changi Airport). The traffic was heavy, the front vehicle slow down, and I also slow down my car to stationary stop for 2-3 second & I heard a hard bang from behind my car.

I went down to check my car was hit by vehicle (Trans taxi: SHD 6338X) the taxi hit my car from behind.

Declaration



Indrawati

21/04/2023

CS CamScanner