



Your Ref: 23.30622

Date: 09th May 2023

Our Ref: CS3/ASM21013327/Dnp3e2-1

M/s HSBC Life (Singapore) Pte Ltd
C/o Seah Ong & Partners LLP
36 Robinson Road #12-03 City House
Singapore 068877
(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FBE 4082L
INSURED VEHICLE: SH 6866L
ACCIDENT DATE: 25/12/2021

We thank you for your instruction on 28/04/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FBE 4082L from M/s Aeon Auto Consultants LLP.
- b) Singapore Accident Statement of Vehicles FBE 4082L and SH 6866L.
- c) Police report of Vehicles FBE 4082L.
- d) Final Repair Bill of FBE 4082L from M/s Tune In Motor. Com.
- e) Colour damaged vehicle photographs of FBE 4082L.

Pre-Repair Inspection Date: 30/12/2021 at M/s Tune In Motor, Blk 1016 Yishun Park A #01-214, Singapore 768758.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: FBE 4082L
Make & Model	: Yamaha T135
Year of Registration	: 2010
Chassis Number	: 5YP301491
Engine Capacity	: 135 cc

- 2. We recommend that the repairs of the entire damage require about 3 (Three) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.