

VEHICLE NO SLZ633U

TOYOTA PRIUS

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)		SURVEYOR'S ADJUSTMENT		
PARTS (LIST ITEMS)							
1	Front bumper <i>De/Torn</i>	REPAIR	<i>78.20</i>	1450.00	✓		
2	Front bumper side retainer @\$98 <i>nts cre o/snn</i>			196.00	<i>1/2 C</i>		
1	Front bumper lower grille <i>11</i>			312.00	X		
1	Front bumper lower skirt <i>11</i>			780.00	X		
1	Front bumper lower cover <i>11</i>			378.00	X		
1	Front bumper fog lamp LHS <i>11</i>			592.50	X		
1	Front bumper fog lamp inner bracket LHS <i>11</i>			142.00	X		
2	Front bumper tow cover @72 <i>11</i>			144.00	X		
1	Front bumper centre badge <i>11</i>			98.00	X		
1	Front bumper centre grille <i>11</i>			372.00	X		
1	LHS Headlamp <i>scr/one</i>			1280.00	✓		
1	LHS Front fender <i>m/sent</i>			982.00	✓		
1	LHS Front fender HYBRID emblem <i>neu</i>			<i>90</i> 126.00	✓		
1	LHS Front fender inner splash shield <i>Torn</i>			245.00	✓		
1	LHS Front door <i>n</i>			0.00	X		
1	LHS Front door glass <i>scr</i>			650.00	X		
1	LHS Side view mirror assy <i>3no</i>			410.00	✓		
1	LHS Side view mirror cover <i>3no</i>			178.00	✓		
1	LHS Side view mirror <i>3no</i>			395.00	✓		
				8730.50			
			less 25%	2182.63	25%		
				6547.88			
SPECIAL NETT ITEMS							
1	Front licence plate w/ holder	REFIX <i>11</i>		0.00	X		
1set	Front bumper clips	<i>neu</i>		80.00	<i>30</i>		
1set	Front fender inner shield clips LHS	<i>neu</i>		60.00	<i>30</i>		
1	Front fender/ bumper securing clip LHS	<i>11</i>		42.00	X		
1	LHS front sports rim	<i>cut N/C</i>		980.00	X		
1	Front bumper lower cover clips	<i>11</i>		60.00	X		
Total Parts				7769.88			

Not Authorised
2/5/23
4 days
1/5 = 3600

p - 445920
252
33444
60
1110
45144
202
3611

VEHICLE NO SLZ633U TOYOTA PRIUS

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas; replace the damaged parts and components.	1000.00	380
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired (front door)	900.00	680
3	To remove and re-fix wiring and check all electrical components at damaged areas and focus headlamp beam	150.00	20
4	To conduct computerised wheel alignment test	120.00	un X
5	To provide anti-rust treatment on affected areas	90.00	30
	Labour Total :	2260.00	
	TOTAL (PARTS & LABOUR):	10029.00	

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

Let Auto Consultants hence notify the Repairer of the following:

- To respray before/after spray painting
- To display damaged parts for survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: