



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL			Ref:	CS3/SMO21002061/TUqy3e2-1
50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Date:	16/05/2023
			Code:	SMO
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJA 76H	Veh. Inspected	SME 7807M
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2100451/RUC	Excess (\$)	0.00
	Assign From		Assign Date	28/04/2023
2. Vehicle Particulars & Condition				
	Make & Model	AUDI TT RS COUP	c.c	2480
	Engine No.	HIDDEN	Year of Reg.	2011
	Chassis No.	TRUZZZ8J7A1901480	Colour	WHITE
	Odometer	112808 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 R17	PIRELLI	6 mm
	L/H Front Tyre	225/45 R17	PIRELLI	6 mm
	R/H Rear Tyre	225/45 R17	PIRELLI	6 mm
	L/H Rear Tyre	225/45 R17	PIRELLI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	08/02/2021	Inspection Date	11/02/2021
	Survey held at	1 GENESIS-BLK 10 AMK INDUSTRIAL PARK 2# 04-01		
	Repairer	-		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	