



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999



T:20221119/2031

3 of 3

Report No. T/20221119/2031

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature of Officer Recording The Report: G / SI Foo Chih Soon	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 19/11/2022 13:24
Officer In Charge Of Case: TP / AEIT / SI ANG YI TING, STEPHANIE Contact No. 65476414	Classification Of Case:

NP158



Enquire Vehicle's Insurance Particulars

Enquire Vehicle's Insurance Particulars (As At 19 Nov 2022 / 08:00:00)

Vehicle Insurance Details

Vehicle No.:

XE388X

Make Description/Model:

VOLVO / FMX410 84RT RAS SC

Insurance Company Name:

LIBERTY INS P L

Business Transaction Reference No.:

20221121135438745041

Please retain the business transaction reference number for Enquire Vehicle Owner Details (if required).

Save as PDF

OK →

Print



You have successfully logged out.

Your last login date and time was 21 Nov 2022, 13:53:43.

To return to ONE.MOTORING, please [click here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No.	Asset Type	Asset ID	Transaction Type
1	Vehicle	XC388X	18.19 Enquire Veh Owner Info (Others) by Law Firm



RECORD MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

9 Temasek Boulevard, Suntec City Tower Two #42-01B
Singapore 038989

E-mail: gears-support@shift-technology.com

GST Registration: M400017735

TAX INVOICE

Date of Request: 05/01/2023

Your Ref No: CL/221138/T/APEX

Dear Sir/Madam,

Date of Accident: 19/11/2022 00:00 (SGT)

Vehicle No: SMN4834G

Place of Accident: Singapore

With reference to your application for the accident report, we have attached the following accident report as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
XE388X	Singapore	(31.00)	1	(28.70)
GST Amount				(2.30)
Total Amount Due (GST Inclusive)				(31.00)

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank you.

This is a computer generated document and requires no signature.

APEX MOTORING

25 Kaki Bukit Road 4 #01-55 S417800

S/no AX-6479

S/no	Description	Amount
1	Parts and labour for repair of Honda Freed Hybrid SMN4834G (Lump Sum)	\$9,400
Total:		\$9,400

Vehicle No:

SMN4834

G

16


December

2022

Date:



Apex Motoring



6 tampines st 73, #01-03, singapore 528825
tel: 6746 2118 fax: 6746 1148
reg no: 53058468m

Claim Reference : -
Insured Vehicle No. : -
Thirty Party Veh No. : -
Officer-In-Charge : -

Our Reference : KAAS/TA/6479/4834/TP/11.22
Invoice No. : 6479
Date : 16 December 2022

To: Advance CR Pte Ltd
c/o 25 Kaki Bukit Road 4
#01-55, Synergy @ Kaki Bukit
Singapore 417800


INVOICE	
PARTICULARS	AMOUNT
Vehicle No. : SMN 4834G Make/Model : Honda Freed Hybrid 1.5G (A)	
<input checked="" type="checkbox"/> Inspection of Vehicle	
<input checked="" type="checkbox"/> Appraisal Report	
<input checked="" type="checkbox"/> 80 Colored Photographs	SGD 725.00
<input checked="" type="checkbox"/> Transport charges	
<input checked="" type="checkbox"/> Re-inspection	
<input type="checkbox"/> Others (Specify)	
Total	SGD 725.00

Dollars: **Seven Hundred and Twenty-Five Only**

(Cheque should be crossed and make payable to " Kelvin Automotive Appraising Services ")



Kelvin Automotive Appraising Services



6 tampines st 73, #01-03, singapore 528825
tel: 6746 2118 fax: 6746 1148
reg no: 53058468m

Claim Reference : -
Insured Vehicle No. : -
Thirty Party Veh No. : -
Officer-In-Charge : -

Our Reference : KAAS/TA/6479/4834/TP/11.22
Date : 16 December 2022

To: Advance CR Pte Ltd
c/o 25 Kaki Bukit Road 4
#01-55, Synergy @ Kaki Bukit
Singapore 417800

VEHICLE APPRAISAL REPORT

Name of Workshop : Apex Motoring
Place of inspection : 25 Kaki Bukit Road 4 #01-55, Synergy @ Kaki Bukit, Singapore 417800
Date of Assignment : 22 November 2022
Date of Accident : 19 November 2022
Date of Inspection : 22 November 2022

PARTICULARS OF INSPECTED VEHICLE

Registration No.	: SMN 4834G	Chassis Frame No.	: GB7-1092183
Make / Model	: Honda Freed Hybrid 1.5G (A)	Engine No. (Logcard)	: LEB5631252
Year of Manufacture/Reg	: 2019	Odometer Reading	: 271,082 KM
Colour	: Silver		
Class / Type	: MPV		

CONDITION OF VEHICLE DURING SURVEY (Visual & Static Check Only)

General Condition : Very Good
Paintwork : Very Good
Market Value : -
Scrap Value : -

CONDITION OF TYRES ON VEHICLE

	<u>Make/Size</u>	<u>Thread Balance</u>
Front L	KAPSEN 185 / 65 R15	7 mm
Front R	KAPSEN 185 / 65 R15	7 mm
Rear L	KAPSEN 185 / 65 R15	7 mm
Rear R	KAPSEN 185 / 65 R15	7 mm

*The above is an estimate of the remaining life of the tyre thread in millimeters

The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this survey report in error, please contact us immediately by phone so that we can arrange for its return.



6 tampines st 73, #01-03, singapore 529825
 tel: 6746 2118 fax: 6746 1148
 reg no: 53058468m

Our Reference : KAAS/TA/64/9/4834/TP/11.22
 Vehicle Number : SMN 4834G

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Conditions	Repairer's Estimate	Revised Amount
LIST ITEMS:-					
1	1 pc	rear bumper	deformed	\$ 1,064.20	\$ 1,064.20
2	2 pcs	rear bumper side retainer @\$47.00	necessary	\$ 94.00	\$ 94.00
3	2 pcs	rear bumper side support @\$79.00	necessary	\$ 158.00	\$ 158.00
4	1 set	rear bumper clips	necessary	\$ 35.00	\$ 35.00
5	1 pc	tailgate	buckled	\$ 1,265.50	\$ 1,265.50
6	1 pc	tailgate chrome garnish	broken	\$ 368.70	\$ 368.70
7	1 pc	tailgate logo emblem	necessary	\$ 77.00	\$ 77.00
8	1 pc	tailgate " freed " emblem	necessary	\$ 64.20	\$ 64.20
9	1 pc	tailgate " hybrid " emblem	necessary	\$ 62.10	\$ 62.10
10	1 pc	tailgate outer handle	damaged	\$ 57.60	\$ 57.60
11	1 pc	tailgate inner lock	jammed	\$ 181.00	\$ 181.00
12	1 pc	tailgate inner trim board	deformed	\$ 331.90	\$ 331.90
13	1 set	tailgate inner trim board clips	necessary	\$ 24.00	\$ 24.00
14	2 pcs	tailgate no. plate lamp @\$25.00	broken	\$ 50.00	\$ 50.00
15	1 pc	tailgate l/h lamp	broken	\$ 380.20	\$ 380.20
16	1 pc	tailgate r/h lamp	broken	\$ 380.20	\$ 380.20
17	1 pc	tailgate weatherstrip	deformed	\$ 194.00	\$ 194.00
18	1 pc	rear windscreen wiper motor	not working	\$ 632.50	\$ 632.50
19	1 pc	rear windscreen glass	broken	\$ 806.00	\$ 806.00
20	1 pc	rear windscreen moulding	necessary	\$ 91.10	\$ 91.10
21	1 pc	l/h taillamp	broken	\$ 667.70	\$ 667.70
22	1 pc	r/h taillamp	broken	\$ 667.70	\$ 667.70
23	2 pcs	taillamp lower filler panel @\$347.60	buckled	\$ 695.20	\$ 695.20
24	1 pc	rear end panel	dented	\$ 717.25	repair
25	1 pc	rear end panel top garnish	deformed	\$ 178.95	\$ 178.95
26	1 pc	l/h rear fender inner trim board	deformed	\$ 570.00	\$ 570.00
27	1 pc	r/h rear fender inner trim board	deformed	\$ 570.00	\$ 570.00
28	1 set	l/h rear fender inner trim board clips	necessary	\$ 35.00	\$ 35.00
29	1 set	r/h rear fender inner trim board clips	necessary	\$ 35.00	\$ 35.00
				\$ 10,454.00	\$ 9,736.75
Less 20%					\$ 1,947.35
				\$ 10,454.00	\$ 7,789.40
SPECIAL NETT ITEMS:-					
30	1 set	reverse sensor	not working	\$ 300.00	\$ 250.00
31	1 set	reverse camera	not working	\$ 480.00	\$ 450.00
32	1 roll	rear windscreen sealant	necessary	\$ 60.00	\$ 40.00
				\$ 840.00	\$ 740.00
Sub - Total				\$ 11,294.00	\$ 8,529.40




6 tampines st 73, #01-03, singapore 528825
 tel: 6746 2118 fax: 6746 1148
 reg no: 53058468m

Our Reference : KAAS/TA/6479/4834/TP/11.22
 Vehicle Number : SMN 4834G

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Conditions	Repairer's Estimate	Revised Amount
		B/F		\$ 11,294.00	\$ 8,529.40
		LABOUR & OTHER CHARGES:-			
1		To panel beat and renewal of all necessary damaged body parts		\$ 1,800.00	\$ 1,600.00
2		To check wiring and rewire		\$ 60.00	\$ 50.00
3		To remove and reinstall tailgate components		\$ 80.00	\$ 60.00
4		To remove and reinstall rear windscreen		\$ 150.00	\$ 120.00
5		To remove and reinstall rear boot upholstery		\$ 120.00	\$ 100.00
6		To remove and reinstall reverse sensor		\$ 140.00	\$ 100.00
7		To remove and reinstall reverse camera		\$ 150.00	\$ 120.00
8		To apply anti-rust		\$ 100.00	\$ 80.00
9		To putty and spray-paint of affected areas		\$ 1,200.00	\$ 1,000.00
				\$ 3,800.00	\$ 3,230.00
Sub - Total				\$ 15,094.00	\$ 11,759.40




6 tampines st 73, #01-03, singapore 528825
 tel: 6746 2118 fax: 6746 1148
 reg no: 53058468m

Our Reference : KAAS/TA/6479/4834/TP/11.22
 Vehicle Number : SMN 4834G

ASSESSMENT SUMMARY

Damages sustained were consistent with the subject vehicle being involved in a collision with another vehicle and the impact was delivered **Squarely to the Rear** portion of the vehicle.



The general area of damages is at the **Rear portion**
 (Please refer to the parts list and photographs as attached for more information)

ASSESSOR'S RECOMMENDATIONS

The estimated repair costs submitted by Messrs **Apex Motoring** is \$ 15,094.00 .
 We have adjusted the cost to \$ 11,759.40 and the repairer has agreed to undertake the repairs at a **Contract Lump Sum of \$ 9,400.00** to a acceptable quality and standards.

However, we have not given authorization and instruction to the repairer to proceed with the repairs.

The repairs should be completed within a reasonable period of **9** working days.

80 photographs were taken at the time of static inspection.

This report is strictly done in a **Without Prejudice Basis**.

We are reverting the matter to you a decision.

We enclose herewith our Invoice No. **6479** for our services rendered and we thank you for engaging our services.

KELVIN AUTOMOTIVE APPRAISING SERVICES

KELVIN TEO
 Licensed Automotive Appraiser
 Nitec in Automotive Technology
 Cert. Crash Investigation & Reconstruction
 Dip MS
 MSAAA, AM SAE-A

NOTE : This revised estimate was from a visual inspection. Should there be any discrepancy or unseen items not listed in this survey, kindly notify the company within Seven (7) days from the date hereof. Otherwise this revised amount shall be treated as valid.

