

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG23004404/UVY3E2**Date:** 24/05/2023REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001866048
<b>Claimant Vehicle No :</b>	SMG5480Z	<b>Insured Vehicle No :</b>	GBH1221G
Date of Loss:	16/03/2023	Nature of Claim:	TP
		Claim No:	307227

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMG5480Z</b>	Engine No:	A2570558N20B20B
Make & Model:	BMW 520I, 2.0 AT D/AB 2WD 4DR LED NAV (A)	Chassis No:	WBA5A32060D333603
Reg. Date:	15/11/2013 (Man. Year: 2013)	Odometer:	144008 km
Colour:	Multi-colour		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,746.85	1,917.09	829.76	30.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,070.00	380.00	690.00	64.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,816.85</b>	<b>2,297.09</b>	<b>1,519.76</b>	<b>39.82</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,800.00</b>		
<b>(S\$)</b>	3,816.85	1,800.00	2,016.85	52.84
<b>+ GST 8.00/8.00% (S\$)</b>	305.35	144.00	161.35	52.84
<b>Nett Amount (S\$)</b>	<b>4,122.20</b>	<b>1,944.00</b>	<b>2,178.20</b>	<b>52.84</b>

INSPECTION

Date of Assignment:	02/05/2023		
Date Inspected:	08/05/2023	Inspected At:	Focus Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #02-48/50 Autobay Singapore 417883
Estimated Period of Repair:	3.0 days		

**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 May 2023)
Parts:	143	BMW 520I 2.0 AT D/AB 2WD 4DR LED NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG5480Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	1,767.00 FL	*1,566.32 FL
2	1		*FRONT BUMPER BEAM	Not Necessary	89.00 FL	*- FL
3	1		*FRONT GRILLE - RH	Scratched	267.00 FL	*186.00 FL
4	1		*FRONT BUMPER STICKER	Necessary	680.00 FS	*300.00 FS
5	1		*FRONT NUMBER PLATE	Scratched	50.00 FS	*40.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (S\$)	2,853.00 2,092.32
					- List Item Discount on L Items 5.00/10.00% (S\$)	106.15 175.23
					Total Parts (S\$)	2,746.85 1,917.09

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING WORK	New	450.00	180.00
2	TO REMOVE & REPLACE BUMPER STICKER	New	220.00	0.00
3	TO SPRAY PAINTING	New	400.00	200.00
<b>Gross Labour Cost (S\$)</b>			<b>1,070.00</b>	<b>380.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >