

Date: 26/04/2023

Vehicle No: SNC8138C

Model: TESLA MODEL 3 STANDARD RANGE

Chassis: LRW3F7FA9MC385502-2021

Reg.Year: 2021

Third Party Insurer: INDIA INSURANCE

Third Party Veh No: XE1404B

Date of Accident: 26/04/2023

Estimator: TING AN

Surveyor:

*Not Notation
Penny B4 paint
6 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR DOOR RH	1		<i>Re</i> \$953.27
2	REAR DOOR WEATHERSTRIP RH	1		<i>Re</i> \$88.79
3	REAR DOOR INNER TRIM BOARD RH	1		\$560.75
4	REAR DOOR REGULATOR RH	1		\$219.63
5	REAR FENDER RH	1		<i>Re</i> \$1,345.79
6	REAR FENDER QUARTER GLASS RH	1		<i>Re</i> \$280.37
7	REAR RIM RH	1		<i>Re</i> \$505.00
8	REAR RIM COVER RH	1		<i>Re</i> \$32.71
9	REAR BUMPER	1		REPAIR
SUB TOTAL				\$3,986.31
COST +10%				\$398.63
PARTS TOTAL				\$4,384.94

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR DOOR INNER TRIM BOARD CLIPS RH	1		\$50.00
2	REAR FENDER QUARTER GLASS SEALANT	1		<i>Re</i> \$80.00
3	REAR TYRE RH	1		<i>Re</i> \$450.00
S/N TOTAL				\$580.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 26/04/2023
Vehicle No: SNC8138C
Model: TESLA MODEL 3 STANDARD RANGE
Chassis: LRW3F7FA9MC385502-2021
Reg.Year: 2021

Third Party Insurer: INDIA INSURANCE
Third Party Veh No: XE1404B
Date of Accident: 26/04/2023
Estimator: TING AN
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

700
\$800.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR DOOR RH, REAR FENDER RH, REAR BUMPER & ETC.

500
\$800.00

LABOUR CHARGES TO REMOVE & REPLACE REAR QUARTER GLASS RH, REAR QUARTER GLASS SEALANT & ETC. TO EFFECT REPLACE OF REAR FENDER RH.

150
\$150.00

LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM RH, UPHOLDSTERY CUSHION SET & ETC. TO EFFECT REPLACE OF REAR FENDER RH.

120
\$350.00

LABOUR CHARGES TO REMOVE & REPLACE REAR RIM RH.

20
\$120.00

TO WHEEL ALIGNMENT & BALANCING.

80
\$80.00

TO TUFF KOTE & UNDERSEAL MATERIALS.

150
\$150.00

TO CHECK WIRING & ELECTRICAL SYSTEM.

120
\$120.00

LABOUR TOTAL **\$2,570.00**

TING AN**TOTAL****\$7,534.94**

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

