



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, S533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#04-05 IOB BUILDING
SINGAPORE 049711

DATE : 24-04-2023

VEHICLE NO. : SMC1435C
ACCIDENT DATE : 21-04-2023 07:15
THIRD PARTY REF. : SND1026H

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE SMC1435C HYUNDAI 130

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	FRONT BONNET <i>Buckled</i>	1502.00 ✓
2	1	FRONT BONNET LOCK <i>new</i>	119.00 +
3	1	FRONT SUPPORT PANEL <i>crushed</i>	1333.00 ✓
4	1	FRONT GRILLE <i>crushed</i>	490.00 ✓
5	1	FRONT GRILLE CHROME <i>crushed</i>	643.00 ✓
6	2	FRONT HEADLAMP@\$1686.00 <i>RH crushed</i>	3372.00 -1686
7	2	FRONT HEADLAMP LOWER BRACKET@\$49.00 ?	98.00 ?
8	1	FRONT BUMPER <i>Deled</i>	1939.00 ✓
9	1	FRONT BUMPER FOAM <i>Deled</i>	233.00 ✓
10	1	FRONT BUMPER REINFORCEMENT <i>new</i>	636.00 +
11	2	FRONT BUMPER SIDE RETAINER@\$41.00 ?	82.00 ?
12	10	FRONT BUMPER CLIP @\$5.00 <i>new</i>	50.00 ✓
13	1	AIR CON CONDENSER <i>new</i>	745.00 X
14	2	AIR CON SIDE GARNISH@\$47.00 <i>new</i>	94.00 X
15	1	RADIATOR <i>new</i>	1209.00 X
16	1	REAR BOOT COVER <i>Deled</i>	2367.00 ✓
17	1	REAR BOOT CENTRE EMBLEM <i>new</i>	49.00 ✓
18	1	REAR BOOT I30 EMBLEM	29.00 ✓
19	1	REAR BOOT 1.4T EMBLEM	28.00 ✓
20	2	REAR BOOT REFLECTOR @\$794.00 <i>LH crushed, RH ?</i>	1588.00 794
21	1	REAR BOOT LOCK <i>Jamned</i>	155.00 ✓
22	1	REAR BOOT RUBBER	288.00 ?
23	1	REAR BOOT TRIMBOARD ?	463.00 ?



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, S533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

VEHICLE NO. : SMC1435C
ACCIDENT DATE : 21-04-2023 07:15
THIRD PARTY REF. : SND1026H

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
24	1	REAR END PANEL <i>Distold</i>	1325.00 ✓
25	1	REAR END PANEL TOP GARNISH ?	219.00 ✓
26	2	REAR LAMP@\$798.00 ?	1596.00 ✓
27	2	REAR LAMP LOWER BRACKET@\$265.00 ?	530.00 ✓
28	1	REAR BUMPER <i>Distold</i>	881.00 ✓
29	1	REAR BUMPER LOWER <i>Distold</i>	331.00 ✓
30	1	REAR BUMPER FOAM ?	248.00 ✓
31	1	REAR BUMPER REINFORCEMENT <i>Distold</i>	434.00 ✓
32	2	REAR BUMPER REINFORCEMENT BRACKET@\$214.00 ?	428.00 ✓
33	5	REAR BUMPER REINFORCEMENT STRIP ?	195.00 ✓
34	1	REAR BUMPER SENSOR ?	169.00 ✓
35	10	REAR BUMPER CLIP @\$5.00 <i>new</i>	50.00 ✓
36	1	REAR SPARE TYRE PANEL ?	940.00 ✓
			24,858.00
			ADD 20 %
			4,971.60
			TOTAL (A)
			29,829.60

SPECIAL NETT ITEMS

1	1	FRONT NUMBER PLATE <i>Distold</i>	40.00 ✓
2	1	REAR NUMBER PLATE <i>Distold</i>	40.00 ✓
3	1	REAR WINDSCREEN GUM <i>new</i>	50.00 ✓
			TOTAL (C)
			130.00

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM(FRONT & REAR)	80.00 ✓ <i>60</i>
2	1	TO REMOVE/REFIT/REFILL AIR CON GAS	120.00 ✓



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, S533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

VEHICLE NO. : SMC1435C
ACCIDENT DATE : 21-04-2023 07:15
THIRD PARTY REF. : SND1026H

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
3	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS (FRONT)	720.00 850
4	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS (REAR)	1080.00 800
5	1	SPRAYPAINTING CHARGES (FRONT) <i>Bumper, Bumper, LH Fender</i>	720.00 600
6	1	SPRAYPAINTING CHARGES (REAR)	1000.00 800
TOTAL (D)			3,720.00
ESTIMATE TOTAL			33,679.60

Adrian L
P/p 27/04/23.
12 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: