

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
Accident Date: 23/04/2023

Estimate No: EST2300161

Date: 25 Apr 2023

Veh Reg No: SKS3875S

Make/Model: TOYOTA
VIOSJGRADEMT

Chasis No: MHFBT9F3006028307

Reg. Date: 13/04/2015

Your Ref No: CB6556C

Estimate Repair Cost to Vehicle No :SKS3875S

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	List Price		
1	1 PC BOOT LID	852.90	
2	2 PCS BOOT LID HINGE	190.00	
3	1 PC BOOT LID LOGO	57.50	
4	1 PC BOOT LID "VIOS" EMBLEM	49.40	
5	1 PC BOOT LID GARNISH	198.80	
6	1 PC BOOT LID LOCK	191.80	
7	1 PC BOOT LID LOCK CHECKER	41.60	
8	1 PC BOOT LID RUBBER	190.10	
9	1 PC BOOT LID TRIM	208.80	
10	1 PC REAR PANEL	775.70	
11	1 PC REAR PANEL TRIM	261.10	
12	1 PC TAIL LAMP - RH	345.90	
13	1 PC TAIL LAMP LH	345.90	
14	1 PC REAR FENDER TRIM RH	261.10	
15	1 PC REAR FENDER TRIM LH	261.10	
16	1 PC REAR BUMPER	665.60	
17	1 PC REAR BUMPER REINFORCEMENT	360.10	
18	2 PCS REAR BUMPER SIDE RETAINER	259.80	
19	2 PCS REAR BUMPER SMALL RETAINERS	97.60	
20	2 PCS REAR BUMPER REFLECTOR	203.60	
21	1 PC REAR SPARE TYRE TOP COVER	234.10	
		6,052.50	
		Less 25%	1,513.13
			4,539.43
	Special Net		
22	1 PC BOOT LID 522 STICKER	35.00	
23	1 SET BOOT LID TRIM CLIPS	60.00	
24	1 SET REAR PANEL TRIM CLIPS	40.00	
25	1 SET REAR FENDER TRIM CLIPS RH	60.00	
26	1 SET REAR FENDER TRIM CLIPS LH	60.00	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
Accident Date: 23/04/2023

Estimate No: EST2300161

Date: 25 Apr 2023

Veh Reg No: SKS3875S

Make/Model: TOYOTA
VIOSJGRADEMT

Chasis No: MHFBT9F3006028307

Reg. Date: 13/04/2015

Your Ref No: CB6556C

Estimate Repair Cost to Vehicle No :SKS3875S

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
27	1 PC REAR FENDER STICKER RH	290.00	
28	1 PC REAR FENDER STICKER LH	290.00	
29	1 PC REAR BUMPER STICKER	280.00	
30	1 PC REAR BUMPER "L" PLATE BRACKET	70.00	
31	1 SET REAR BUMPER CLIPS	60.00	
		1,245.00	1,245.00
	Labour		
32	1 TO CHECK WIRING	50.00	
33	1 TO REPLACE STICKER	120.00	
34	1 TO REMOVE AND REFIT REAR INNER TRIM	80.00	
35	1 TO SPRAY PANEL SEALANT	100.00	
36	1 TO SPRAY PAINTING DAMAGED PORTION, INCLUDING SUPPLY OF PAINT MATERIALS SUCH AS MASKING TAPE, SAND PAPERS, PRIMER, POLISHING COMPOUND AND CHEMICAL ETC.	1,300.00	
37	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,200.00	
		2,850.00	2,850.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
Accident Date: 23/04/2023

Estimate No: EST2300161

Date: 25 Apr 2023

Veh Reg No: SKS3875S

Make/Model: TOYOTA
VIOSJGRADEMT

Chasis No: MHFBT9F3006028307

Reg. Date: 13/04/2015

Your Ref No: CB6556C


Estimate Repair Cost to Vehicle No :SKS3875S

Quantity	Description	List Price	Amount
		S\$	S\$
		Total	S\$ 8,634.43
		Add GST @ 8%	690.75
		Total Amount Payable	S\$ 9,325.18

TOTAL: SINGAPORE DOLLAR NINE THOUSAND THREE HUNDRED TWENTY FIVE AND CENTS EIGHTEEN ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd


AUTHORISED SIGNATURE