



ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 2997E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER COVER	SCRATCHED	459.40	459.40
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER CENTRE MOULDING ASSY	CRACKED	451.25	451.25
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	394.80	-
2	REAR BUMPER REINFORCEMENT BRACKET LH RH @ \$138.10	NOT NECESSARY	276.20	-
2	REAR BUMPER SIDE BRACKET LH RH @\$55.80	NOT NECESSARY	111.60	-
1	BOOTLID	DENTED	2,549.70	2,549.70
1	BOOTLID HYUNDAI PLATE	NOT NECESSARY	24.30	-
1	EMBLEM HYBRID	NECESSARY	24.30	24.30
1	EMBLEM - IONIQ	NECESSARY	31.30	31.30
1	ANTENNA SMARTKEY	NOT NECESSARY	40.50	-
1	REAR BUMPER FOG LAMP	NOT NECESSARY	201.50	-
1	REAR BUMPER LOWER CTR MOULDING	NOT NECESSARY	155.00	-
1	REAR BUMPER UNDER CTR COVER	NOT NECESSARY	225.00	-
1	REAR END PANEL GARNISH	NOT NECESSARY	346.80	-
1	REAR END PANEL	NOT NECESSARY	532.00	-
	LESS 20% DISCOUNT		-1,169.13	-707.59
			4,676.52	2,830.36
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE WITH TRIM COVER (SN)	DENTED	50.00	50.00
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
1	BOOTLID COMFORT TEL NO STICKER (SN)	NECESSARY	40.00	40.00
1	BOOTLID COMFORT LOGO STICKER (SN)	NECESSARY	30.00	30.00
1	BOOTLID COMFORT APP STICKER (SN)	NECESSARY	30.00	30.00
1	REAR BUMPER REVERSE SENSOR (SN)	FAULTY	180.00	180.00
			380.00	380.00
LABOUR				
	PANEL BEATING.		1,100.00	1,050.00



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING CHARGE.	NOT NECESSARY	800.00	750.00
	REMOVE/REFIX BOOTLID GLASS.		120.00	80.00
	TUFF KOTE.		60.00	-
	REMOVE/REFIX REVERSE SENSOR.		80.00	30.00
			2,160.00	1,910.00
	GRAND TOTAL		7,216.52	5,120.36
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			4,100.00

Report Ref No. NS/INC23004413/Sqp3m4

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.