

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHB2997E

Make : HYUNDAI

Model : IONIQ(G3)

Date: 17/04/2023

Insurance: INCOME

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER <i>Sur</i>			\$459.40
10	REAR BUMPER CLIPS <i>NCC</i>			\$22.00
1	REAR BUMPER CENTRE MOULDING ASSY <i>Cra</i>			\$451.25
1	REAR BUMPER REINFORCEMENT <i>?XNV</i>			\$394.80
1	REAR BUMPER REINFORCEMENT BRACKET LH RH <i>?XNV</i>		\$138.10	\$276.20
2	REAR BUMPER SIDE BRACKET LH RH <i>XNV</i>		\$55.80	\$111.60
1	BOOTLID <i>Dmt</i>			\$2,549.70
1	BOOTLID HYUNDAI PLATE <i>NCC</i>			\$24.30
1	EMBLEM HYBRID <i>NCC</i>			\$24.30
1	EMBLEM - IONIQ <i>NCC</i>			\$31.30
1	ANTENNA SMARTKEY <i>? X NV</i>			\$40.50
1	REAR BUMPER FOG LAMP <i>?XNV</i>			\$201.50
1	REAR BUMPER LOWER CTR MOULDING <i>?XNV</i>			\$155.00
1	REAR BUMPER UNDER CTR COVER <i>X NV</i>			\$225.00
1	REAR END PANEL GARNISH <i>? X NV</i>			\$346.80
1	REAR END PANEL <i>?X NV</i>			\$532.00
	SUB TOTAL		3562.25	\$5,845.65
	LESS 20%		712.45	\$1,169.13
	DISCOUNTED TOTAL		2849.80	\$4,676.52
	REAR NUMBER PLATE WITH TRIM COVER <i>Dmt</i>			\$50.00
	REAR BUMPER RUBBER MAT <i>NCC</i>			\$50.00
	BOOTLID COMFORT TEL NO STICKER <i>NCC</i>			\$40.00
	BOOTLID COMFORT LOGO STICKER <i>NCC</i>			\$30.00
	BOOTLID COMFORT APP STICKER <i>NCC</i>			\$30.00
	REAR BUMPER REVERSE SENSOR <i>factory</i>			\$180.00
		NETT		\$380.00
	Labour Charge			\$1,100.00
	PANEL BEATING			\$800.00
	SPRAY PAINTING CHARGE			\$120.00
	REMOVE/REFIX BOOTLID GLASS			\$60.00
	TUFF KOTE			\$80.00
	REMOVE/REFIX REVERSE SENSOR			\$80.00
	TOTAL LABOUR			\$2,160.00
	ESTIMATE TOTAL		5131.80	\$7,216.52

LKK Auto Consultants hence notify the Repairer of the following:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the insurance company. 2051027.96

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

= 4111.84 4 days 1 day
 ~4100 X L/S
 17724123
 3 30pm