



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI23004415/Kqy3e2	Date: 03/07/2023
			Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMN 9141P	Veh. Inspected	SKW 5746Y	
Policy No.	P10526203R02	Coverage (\$)	0.00	
Claim No.	C10021906 /CH	Excess (\$)	0.00	
Assign From	FRAULEINE KHOO	Assign Date	02/05/2023	
2. Vehicle Particulars & Condition				
Make & Model	HONDA ODYSSEY (A)	c.c	2356	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JHMRC1890FC205011	Colour	METALLIC DARK BLUE	
Odometer	79019 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	TRIANGLE	7 mm	
L/H Front Tyre	215/55 R17	TRIANGLE	7 mm	
R/H Rear Tyre	215/55 R17	TRIANGLE	8 mm	
L/H Rear Tyre	215/55 R17	TRIANGLE	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/04/2023	Inspection Date	15/05/2023	
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	