



Pte Ltd

TeamWork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475

E-mail : claims@teamworkgarage.com

ROC number : 201015366H

REPAIR PERFORMANCE INVOICE



Vehicle number SME8407C
Make / Model TOYOTA NOAH
Chassis number ZWR800331439
Accident date 28/4/23
Reference 2304-45

TP Sompoo
Xiao Chu.

Qty Particulars Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1	REAR BUMPER <i>Del</i>	700.70 ✓
1	REAR BUMPER RETAINER <i>new</i>	189.20 ✓
2	REAR BUMPER REFLECTOR <i>new</i>	144.00 ✓
2	REAR CORNER BUMPER <i>Del</i>	420.20 ✓
1	TAILGATE <i>Del</i>	2040.00 ✓ 1812
1	TAILGATE EMBLEM - HYBRID <i>new</i>	67.85 ✓
1	TAILGATE LOCK <i>Tam</i>	542.40 ✓ 375
1	TAILGATE LOCK STRIKER <i>new</i>	58.00 ✓
1	TAILGATE WEATHERSTRIP <i>Del</i>	433.40 ✓ 385
1	TAILGATE INNER TRIM BOARD <i>Del</i>	825.00 ✓ 745
2	TAILGATE ABSORBER <i>new</i>	776.60 ✓
1	TAILGATE GLASS MOULDING <i>new</i>	77.06 ✓
1	TAILGATE WINDSCREEN GLASS <i>Shattered</i>	1362.00 ✓
1	TAILGATE CHROME GARNISH <i>Del</i>	1008.70 ✓ 581
1	TAILGATE EMBLEM - LOGO <i>new</i>	73.00 ✓
1	TAILGATE UPPER TRIM BOARD <i>new</i>	228.80 ✓
2	TAILGATE UPPER TRIM BOARD LH / RH <i>Del</i>	330.00 ✓
1	KEYLESS SPEAKER <i>new</i>	165.00 ✓
1	END PANEL <i>Del</i>	809.27 ✓ 735
1	END PANEL INNER GARNISH <i>Del</i>	281.52 ✓
1	END PANEL TOP GARNISH <i>Del</i>	186.00 ✓
1	KEYLESS ANTENNA <i>Del</i>	227.70 ✓
1	SPARE TYRE PANEL <i>new</i>	837.60 ✓
1	SPARE TYRE TOP BOARD <i>Del</i>	1175.00 ✓ 691
2	REAR FENDER INNER TRIM <i>2nd Del</i>	1386.00 ✓ 780
2	TAILLAMP <i>2nd Del, R/L int.</i>	1588.40 ✓
1	WIPER ARM <i>new</i>	110.00 ✓
1	WIPER BLADE <i>new</i>	75.00 ✓
1	WIPER MOTOR <i>new</i>	843.00 ✓
1	THIRD BRAKE LIGHT <i>new</i>	262.00 ✓
1	REAR PASSENGER SEAT <i>new</i>	1120.30 ✓
1	REAR PASSENGER SEAT HEADREST <i>new</i>	876.90 ✓
		19220.60
Less 25%		4805.15
		14415.45

PARTS REPLACEMENT - SPECIAL NETT ITEMS		
1 SET	REAR BUMPER CLIP <i>new</i>	30.00 ✓
1 SET	TAILGATE INNER TRIM BOARD CLIP <i>new</i>	30.00 ✓
1 SET	END PANEL TOP GARNISH CLIP <i>new</i>	30.00 ✓
1 SET	REAR FENDER INNER TRIM CLIP <i>new</i>	60.00 ✓
1	TAILGATE GLASS SEALANT <i>new</i>	120.00 ✓
1	REAR NUMBER PLATE <i>new</i>	80.00 ✓
1	REAR INCAR CAMERA <i>new</i>	600.00 ✓
1	JOINT SEALANT <i>new</i>	120.00 ✓

680

<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
1	CHECK WIRING AND LIGHTNING SYSTEM	60.00 30
2	REMOVE & REPLACE PDC SENSOR	150.00 50
3	REMOVE & REPLACE TAILGATE GLASS	150.00 120
4	REMOVE TRIMS AND GARNISHES TO FACILITATE REPAIR	200.00 60
5	REMOVE & RESET HEADREST	300.00 x.
6	VACUMN ON SHUTTLED TAILGATE GLASS	120.00 60
7	PANEL BEATING ON AFFECTED AREAS	1600.00 800
8	SPRAY PAINTING ON AFFECTED AREAS	1600.00 800
9	APPLY ANTI RUST ON AFFECTED AREAS	450.00 60
Subtotal		4330.00
Grand total		19815.45

1980

Adrian L
 r/c 03/05/23.
 06 Days

total: 11154.05
 r/s 8-8k

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

knownedged by Repairer
 Signature: