



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/TP/0412/2023/EQ  
**DATE** : 27-Apr-23  
**WIP** : 17884

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON  
YOUR INSURED VEH NO : SLQ 6113 L**

**China Taiping Insurance (S) Pte Ltd**

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

Attn: Motor Claims Dept

**OWNER'S NAME** : MR MOHAMED SHAKIR BIN SHEIK ALI  
**ADDRESS** : BLK 715 CLEMENTI WEST STREET 2  
#02-61  
SINGAPORE 120715  
**TELEPHONE** : HP +65 90124740  
**TYPE OF CLAIM** : THIRD PARTY CLAIM  
**POLICY NO** : 5126057168  
**VEHICLE NO** : **SLN 1875 U**  
**MODEL CODE** : TOYOTA SIENTA 1.5X C  
**MODEL YEAR** : 25/4/2017  
**ENGINE NO** : 2NR8609864  
**CHASSIS NO** : NSP1707029973  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 22-Apr-23  
**PLACE OF ACCIDENT** : PANDAN GARDENS CARPARK

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLN 1875 U**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,800.00	
4	TO RESPRAY FRONT BUMPER, BONNET AND LHS FRONT FENDER.	\$	3,000.00	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 6,702.00</b>	

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLN 1875 U**

			<b>DAMAGED PARTS &amp; PRICES</b>	
<b>S/N</b>	<b>PARTS DESCRIPTION</b>	<b>QTY</b>	<b>S/NETT</b>	<b>REMARKS</b>
1	FRONT BUMPER	1	\$ 540.00	
2	FRONT BUMPER SIDE RETAINER - LH / RH	2	\$ 210.00	
3	RADIATOR GRILLE	1	\$ 960.00	
4	HEADLAMP - LH	1	\$ 3,450.00	
5	FRONT BUMPER FOAM	1	\$ 120.00	
6	FRONT BUMPER BEAM	1	\$ 360.00	
7	BONNET	1	\$ 780.00	
8	BONNET HINGE - LH / RH	2	\$ 210.00	
9	FRONT NUMBER PLATE	S/N	\$ 60.00	
10	SUNDRIES		\$ 300.00	
<b>TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$ 6,990.00</b>	
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 6,702.00</b>	
<b>GRAND TOTAL</b>		<b>:</b>	<b>\$ 13,692.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND:      REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
                  SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT