



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0412/2023/EQ
DATE : 27-Apr-23
WIP : 17884

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON
YOUR INSURED VEH NO : SLQ 6113 L**

China Taiping Insurance (S) Pte Ltd

3 Anson Road
#16-00 Springleaf Tower
Singapore 079909
Attn: Motor Claims Dept

OWNER'S NAME : MR MOHAMED SHAKIR BIN SHEIK ALI
ADDRESS : BLK 715 CLEMENTI WEST STREET 2
#02-61
SINGAPORE 120715
TELEPHONE : HP +65 90124740
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 5126057168
VEHICLE NO : **SLN 1875 U**
MODEL CODE : TOYOTA SIENTA 1.5X C
MODEL YEAR : 25/4/2017
ENGINE NO : 2NR8609864
CHASSIS NO : NSP1707029973
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 22-Apr-23
PLACE OF ACCIDENT : PANDAN GARDENS CARPARK



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLN 1875 U

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	200
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	200
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	@700 \$	2,800.00	600
4	TO RESPRAY FRONT BUMPER, BONNET AND LHS FRONT FENDER.	@750 \$	3,000.00	700
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	
TOTAL LABOUR CHARGES			\$ 6,702.00	




55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLN 1875 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>de/</i>	1	\$ 540.00	
2	FRONT BUMPER SIDE RETAINER - LH / RH <i>?</i>	2	\$ 210.00	
3	RADIATOR GRILLE <i>ca/</i>	1	\$ 960.00	
4	HEADLAMP - LH <i>ca/</i>	1	\$ 3,450.00	
5	FRONT BUMPER FOAM <i>?</i>	1	\$ 120.00	
6	FRONT BUMPER BEAM <i>?</i>	1	\$ 360.00	
7	BONNET <i>bt/</i>	1	\$ 780.00	
8	BONNET HINGE - LH / RH <i>?</i>	2	\$ 210.00	
9	FRONT NUMBER PLATE <i>bt/</i>	S/N	\$ 60.00	
10	SUNDRIES <i>?</i>		\$ 300.00	
TOTAL SPARE PARTS		:	\$ 6,990.00	
TOTAL LABOUR CHARGES		:	\$ 6,702.00	
GRAND TOTAL		:	\$ 13,692.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Rama - 4p - 900 / 0068*
 SURVEYED DATE : *04/05/23 @ 1400*
 AUTHORISED DATE :
 EXCESS COST :
 LIABILITY :
 REMARKS : *S deep*
P/P
Resury before paint

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 805I

Vehicle Details

Vehicle No.: SLN1875U

Vehicle to be Exported: No

Intended Deregistration Date: 05 May 2023

Vehicle Make: TOYOTA

Vehicle Model: SIENTA 1.5X CVT

Primary Colour: Yellow

Manufacturing Year: 2016

Engine No.: 2NR8609864

Chassis No.: NSP1707029973

Maximum Power Output: 80.0 kW (107 bhp)

Open Market Value: \$20,594.00

Original Registration Date: 25 Apr 2017

First Registration Date: 25 Apr 2017

Transfer Count: 1

Actual ARF Paid: \$10,832.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 24 Apr 2027

PARF Rebate Amount: \$7,040.00

Intended COE Rebate Details

COE Expiry Date: 24 Apr 2027

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$52,000.00

COE Rebate Amount: \$20,641.00

Total Rebate Amount: \$27,681.00

Toyota Sienta Hybrid 1.5A X

[Overview](#)

[Financial](#)

[Insurance](#)

[Accessories](#)

[Similar](#)

[Research](#)

[Photos](#)



4 FOR WHEEL

Price	\$73,888		
Depreciation ⓘ	\$15,480 /yr View models with similar depre	Reg Date	14-Dec-2017 (4yrs 7mths 8days COE left)
Mileage	52,000 km (9.6k /yr)	Manufactured ⓘ	2017
Road Tax ⓘ	\$682 /yr	Transmission	Auto
Dereg Value ⓘ	\$20,100 as of today (change)	Fuel Type	Petrol-Electric
COE ⓘ	\$36,001	OMV	\$23,753
Engine Cap	1,496 cc	ARF ⓘ	\$5,000
Curb Weight ⓘ	1,380 kg	Power	73.0 kW (97 bhp)