





# SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133

T 65 6758 2222 F 65 6257 6931

E sales@scauto.com.sg

scauto.com.sg

Co. Reg. No. 199800107D

M/S ALLIANZ INSURANCE  
SINGAPORE PTE LTD  
79 ROBINSON ROAD #09-01  
SINGAPORE 068897

Insured TONG TAR TRANSPORT SERVICE  
PTE LTD

Policy 5128761629-000039

## ESTIMATE

GST Reg. No: 199800107D

Date: 2/5/2023

Our Case Ref.

Accident Date 27/4/2023

Damaged Vehicle No: PC861B

| S/no                  | Description                                                            | QTY   | Price      | Amount      | Remark  |
|-----------------------|------------------------------------------------------------------------|-------|------------|-------------|---------|
| <b>Replaced Parts</b> |                                                                        |       |            |             |         |
| 1                     | SIGNAL LIGHT UPPER RH                                                  | 1 PC  | \$ 265.30  | \$ 265.30   | over    |
| 2                     | SIGNAL LIGHT LOWER RH                                                  | 1 PC  | \$ 216.10  | \$ 216.10   | over    |
| 3                     | ARTWORK                                                                | 1 PC  | \$ 800.00  | \$ 800.00   | 600     |
| 4                     | INFORMATION STICKER                                                    | 1 PC  | \$ 80.00   | \$ 80.00    | int 25  |
| 5                     | SIDE FLIP COVER FRONT RH                                               | 1 PC  | \$1,650.00 | \$ 1,650.00 | Ry      |
| 6                     | SIDE FLIP COVER FRONT RH LOCK                                          | 1 PC  | \$ 155.00  | \$ 155.00   | Ry      |
| 7                     | SIDE FLIP COVER FRONT RH HOLDER                                        | 1 PC  | \$ 280.00  | \$ 280.00   | Ry      |
| 8                     | SIDE PANEL RH                                                          | 1 PC  | TBC        | TBC         |         |
| 9                     | SEALANT                                                                | 10 PC | \$ 490.00  | \$ 490.00   | rel 245 |
| 10                    | SUNDRIES                                                               | 1     | \$ 250.00  | \$ 250.00   | 50      |
| <b>Labour Charges</b> |                                                                        |       |            |             |         |
| 1                     | LABOUR TO REMOVE AND REINSTALL WIRE HARNESS. CHECK ACCORDING TO DAMAGE |       | \$ 350.00  | \$ 350.00   | 200     |
| 2                     | REMOVE AND REINSTALL SIDE GLASS RH                                     |       | \$1,200.00 | \$ 1,200.00 | 500     |
| 3                     | LABOUR TO REMOVE, REPAIR AND REINSTALL FRONT PORTION RH. 640           |       | \$5,120.00 | \$ 5,120.00 | 2560    |
| 3                     | LABOUR TO RESPRAY FRONT PORTION RHS. 640                               |       | \$4,500.00 | \$ 4,500.00 | 2560    |
| 4                     | LABOUR TO CARRY OUT DIAGNOSTIC CHECK.                                  |       | \$ 250.00  | \$ 250.00   | X       |

Tanpin 97495749  
3/5/23 03 pm  
L/S Resey after repair  
Tanpin 21/05/2023  
7-8 days

LKK Auto Consultants to be notified by the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Third party survey is on a Without Prejudice basis  
No illegal modification is allowed

Supplementary to (s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL \$15,806.40