

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 13 Jul 2023

**Preliminary Advice**

|                    |                                                                                                                   |                         |              |
|--------------------|-------------------------------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SMP1219S                                                                                                        | Accident Date           | : 25/04/2023 |
| TP Vehicle No      | : FBP9906U                                                                                                        | Assignment Date         | : 02/05/2023 |
| Make               | : YAMAHA AEROX 155A                                                                                               | Est. Duration of Repair | : 3          |
| Date of Inspection | : 02/05/2023                                                                                                      |                         |              |
| Inspection At      | : BAN HOCK HIN CO. PTE LTD (HQ)<br>BLK 8 DEFU SOUTH STREET 1, #04-28 JTC DEFU INDUSTRIAL CITY<br>SINGAPORE 533758 |                         |              |

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |          |              |
|-----------------------------|----------|--------------|
| Repairer's Estimate (Gross) | :S\$     | 2,837.00     |
| Revised Amount              | :S\$     | 1,591.80     |
| Check Items (Estimated)     | :S\$     | 0.00         |
| Total                       | :S\$     | 1,591.80     |
| <br>Lump Sum Repair         | <br>:S\$ | <br>1,250.00 |

**Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.