

(08/11/13) wef

ASS. REC. BY: Morris

REF:

CC4/AIS23004432/4p3

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNB 7125B

at Workshop m/s G9 lxy

of \_\_\_\_\_

Insured: SJS 15940

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: 892k

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: 214542861

Veh No: SNB 7125B Yr Regn: 16/04/18

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or A / 1.5 Turbo

Make: Honda civic c.c. 1498

Colour: Red/Grey A/C: Insured / Std / NI / NA

Sp. Reading: 92945 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MRHFK4840HT000022

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: 235/4022R

ES DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 21/04/23

Survey held at \_\_\_\_\_

Rear

R/Bal. 7 mm

L/Bal. 876/23 mm

D.O.I. 8/6/23

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 27/6/23

12/6/23 wrap sticker  
2/3 \$1600 in hand Alex

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ Site Insp (\$ \_\_\_\_\_)

☐ Interview (\$ \_\_\_\_\_)

☐ Tech. Invs (\$ \_\_\_\_\_)

☐ Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

☐ S + RS, ☐ SI

Photos

Others

TOTAL

# **GALAXY AUTO CARE PRIVATE LIMITED**

Bartley Biz Centre 13 Kaki Bukit Road 4 #01-23 Singapore 417807

Tel: 9010 8488/ Email: galaxyautosg@gmail.com

VEHICLE NO: SNB7125B

MAKE & MODEL: HONDA CIVIC

DOA: 21.04.2023

CLAIM TYPE: TP CLAIM

*not Authen  
2/5 81600  
8/6/23  
2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To resurvey damaged part(s) during resurvey
- Resurvey subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## **ESTIMATION QUOTE**

| PARTS                                      | QTY | PRICE (\$)       | REMARKS            |
|--------------------------------------------|-----|------------------|--------------------|
| FRONT BUMPER                               | 1   | \$ 1,273.00      | 20/0e ✓            |
| FRONT BUMPER RETAINER LH                   | 1   | \$ 98.00         | 11 X               |
| FRONT BUMPER RETAINER RH                   | 1   | \$ 98.00         | 11 X               |
| FRONT BUMPER REINFORCEMENT                 | 1   | \$ 509.50        | 8e X               |
| FRONT BUMPER GRILLE                        | 1   | \$ 458.00        | 7w1/Cne ✓          |
| FRONT BUMPER LOWER GRILLE                  | 1   | \$ 325.00        | 7w1 ✓              |
| FRONT BUMPER LOWER LIP                     | 1   | \$ 328.00        | 11 X               |
| FRONT BUMPER FOG LAMP LH                   | 1   | \$ 280.00        | 11 X               |
| FRONT BUMPER FOG LAMP RH <i>Garnish RH</i> | 1   | \$ 280.00        | Cne ✓              |
| FRONT BUMPER LOGO                          | 1   | \$ 108.00        | 11 X               |
| FRONT HEADLAMP LH                          | 1   | \$ 2,400.00      | 11 X               |
| FRONT HEADLAMP RH                          | 1   | \$ 2,400.00      | 11 X               |
|                                            |     | \$ 8,557.50      |                    |
|                                            |     | LESS 20%         | \$ 1,711.50        |
|                                            |     | <b>SUB TOTAL</b> | <b>\$ 6,846.00</b> |

| SPECIAL NETT ITEMS | QTY   | PRICE (\$)       | REMARKS          |
|--------------------|-------|------------------|------------------|
| FRONT BUMPER CLIP  | 1 SET | \$ 50.00         | 11 30            |
| FRONT GRILLE CLIP  | 1 SET | \$ 50.00         | 11 X             |
| FRONT NUMBER PLATE | 1 SET | \$ 90.00         | Cne 40           |
| JOINT SEALANT      | 1     | \$ 100.00        | 11 X             |
|                    |       | <b>SUB TOTAL</b> | <b>\$ 290.00</b> |

*1 pc*

*front bumper wrap sticker #200 11 ✓*

| LABOUR                                                             | QTY | PRICE (\$)  | REMARKS |
|--------------------------------------------------------------------|-----|-------------|---------|
| CHECK WIRING AND LIGHTING SYSTEM ON ACCIDENT DAMAGED AREA          | 1   | \$ 100.00   | 20      |
| REMOVE AND REFIT LINING, TRIM AND GARNISH ON ACCIDENT DAMAGED AREA | 1   | \$ 150.00   | 11 X    |
| PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS             | 1   | \$ 1,000.00 | 200     |
| SPRAY PAINTING ON AFFECTED AREAS                                   | 1   | \$ 1,000.00 | 300     |
| APPLY ANTI RUST ON AFFECTED AREAS                                  | 1   | \$ 100.00   | 11 X    |

**SUB TOTAL \$ 2,350.00**

*2-1511-2  
202  
1208.96  
290  
520  
1614 2018-86*

GRAND TOTAL \$ 9,486.00