

PORT:

REF:

ASS. REC. BY:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claim No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

4

days

Rest: Yes or No

Lump Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMC1196B

Yr Regt: 29 DEC 2016

Type: M/Gar / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

HYUNDAI I-40

CC 1685

Colour:

Blue

AC: Insured / Std / N/A

Sp. Reading:

Unable to start

T/Radio: Insured / Std / NI / NA

Eng No:

C/Nr:

KMHLB41UMH097728

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NI / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

195 / 85 R15

BS / DUN / EXNOVA / GY / FS / LZA / WIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal:

5

mm

R/Bal:

5

mm

L/Bal:

5

mm

L/Bal:

5

mm

D.O.A. 28/04/23

D.O.I. 02/05/23 3-30pm

Survey held at

CDGE

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

2 FRT O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Balance:

yearly:

MV:

NI:

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1) Date/Time, File Return to?

2)

Report Format:

Lump Sum / L.B.I: (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ + RS: \$

Photos:

Others:

TOTAL

Date/Time: 28.04.2023 14:57

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5894813

JC NO305552997

OMER

S COMFORT TRANSPORTATION PTE LTD

OMER NO. 7010045

ESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

(R) 65508755

(P) (O)

JUNT CARD NO.

REGN NO.:

SHC1196B

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

I-40

DATE/TIME IN 28.04.2023 11:20

YR OF MANU.

29.12.2016

TARGET DATE

CHASSIS CODE

KMHLB41UMHU097728

COMPLETION DATE/TIME:

JOB DESCRIPTION


Incident Date: 28.04.2023

ATURE: 3P 28.04.2023

NO

LABOR CODE

DESCRIPTION



ED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

gement Slip

Exit Pass

o.: SHC1196B

YY

Vehicle No.:

SHC1196B

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 28 Apr 2023)**Parts:** 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHC1196B/28/04/2023 15:20**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER COVER <i>deform</i>	20.00	0.00	*553.00 FL
2	1		*REAR BUMPER CLIPS <i>has Repeat</i>	20.00	0.00	*22.00 FL
3	1		*REAR BUMPER REINFORCEMENT ?	20.00	0.00	*428.40 FL
4	1		*REAR BUMPER LOWER COVER <i>scr</i>	20.00	0.00	*228.00 FL
5	1		*BOOTLID <i>R</i>	20.00	0.00	*2,174.90 FL
6	1		*BOOTLID H EMBLEM <i>Nec</i>	20.00	0.00	*63.10 FL
7	1		*BOOTLID CRDI PLATE <i>Nec</i>	20.00	0.00	*52.40 FL
8	1		*BOOTLID MOULDING <i>Nec</i>	20.00	0.00	*85.00 FL
9	1		*BOOTLID I40 EMBLEM <i>Nec</i>	20.00	0.00	*67.90 FL
10	1		*FRT BUMPER COVER <i>scr</i>	20.00	0.00	*1,052.20 FL
11	1		*FRT & RR BUMPER CLIPS <i>Nec</i>	20.00	0.00	*44.00 FL
12	1		*FRT BUMPER REINFORCEMENT ?	20.00	0.00	*588.40 FL
13	1		*HEADLAMP LH ?	20.00	0.00	*1,388.00 FL
14	1		*HEADLAMP RH ?	20.00	0.00	*1,388.00 FL
15	1		*HEADLAMP SUPPORT PANEL ASSY ?	20.00	0.00	*907.40 FL
16	1		*RADIATOR GRILLE <i>215m</i>	20.00	0.00	*1,480.00 FL
17	1		*RADIATOR GRILLE H EMBLEM ?	20.00	0.00	*129.50 FL
18	1		*FRT BUMPER SIDE BRACKET LH ?	20.00	0.00	*24.60 FL
19	1		*FRT BUMPER SIDE BRACKET RH ?	20.00	0.00	*24.60 FL
20	1		*RENEW ADVERTISEMENT STICKER <i>Nec</i>	0.00	0.00	*50.00 F
21	1		*REAR REVERSE SENSOR <i>Faulty</i>	0.00	0.00	*135.70 F
22	1		*FRT NUMBER PLATE WITH TRIM COVER ?	0.00	0.00	*55.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	10,942.10
- List Item Discount on L Items (S\$)	2,140.28
Total Parts (S\$)	8,801.82

ComfortDelGro Engineering Pte Ltd/SHC1196B/28/04/2023 15:20. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: India International Insurance Pte Ltd (HQ)
CTPL

Singapore

Loke Wei Yiong

UKK

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	28/04/2023
Vehicle Reg. No.:	SHC1196B	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI I40, 1.7 D CRDI (A)	Vehicle Reg. Date:	29/12/2016
Vehicle Colour:	BLUE		
Engine No:	D4FDGU700056	Chassis No:	KMHLB41UMHU097728
Odometer:	684029 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Remarks:	TEL: 62148355		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	8,801.82
Miscellaneous Items	11.00
Labour	1,920.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	10,732.82
+ GST 8.00% (\$)	858.63
Nett Amount (\$)	11,591.45

This claim is handled by: MS. LOKE YY

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	1,000.00 840
2	SPRAY PAINTING CHARGE	New	800.00 700
3	REMOVE/ REFIX REAR REVERSE SENSOR	New	60.00 20
4	CHECK LIGHTING	New	60.00 30
Gross Labour Cost (S\$)			1,920.00

ComfortDelGro Engineering Pte Ltd/SHC1196B/28/04/2023 15:20. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

4 days

L/S

2/5/23 330pm

18/4