



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMS1387Z

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information

WIP No **64624**
Reg No/Reg Date **SMS1387Z / 12/02/2020**
Date In/Mileage **/ 13481**
Chassis No **WDC1569422J6839035**
Engine No **27091031942293**
Make/Model **MB/GLA 180 SPORT UTILITY VEH**
Colour/Trim **021 191 Cosmos Blac/ 043 381 ARTICO/FabB**

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WA000001	Credit	28/04/2023/ 19:22	CH	371 / Go Chee Han					
THIS IS NOT AN OFFICIAL TAX INVOICE ESTIMATE									
7 REQUEST Customer Request M BPNSUN POLICY NO/ACC DATE : 2070014277-03 // 24-4-2023 TOW IN/TP VEH NUMBER : 28-4-2023 // YRIG - ALLIANZ DATE IN/DATE SURVEY: DIRECT SETTLEMENT BY: S BPNTOW ACCIDENT TOWING FROM 517 AIRPORT ROAD TO PLSC USING: KING DOLLEY REFER WO: 1319529 A BPILAB PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS AND REFINISH. A BPIRES RESPRAY FRONT BUMPER & ENGINE HOOD & LH/FRONT FENDER & RH/FRONT FENDER REAR BUMPER & TAILGATE & LH/REAR FENDER & RH/REAR FENDER & END PANEL REAR SPOILER & LH/FRONT DOOR & RH/FRONT DOOR A BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT A BPILAB TO REMOVE, REPLACE HEADLAMP WITH FOCUS . NETT S BPNSUB SUPPLY 1 SET FRONT NUMBER PLATE WITH HOUSING. NETT A BPILAB REMOVE, REPLACE RADIATOR, CONDENSER COOLING SYSTEM & FITTINGS- VACUUM AND REGAS . NETT A BPILAB TO REMOVE/REPLACE AFFECTED SEAT BELTS A BPILAB PLACE VEHICLE ON-TO CELLETTE BENCH & CONDUCT CHASSIS ALIGNMENT. NETT <i>photo</i> A BPILAB									
									150.00
									1400.00
									9600.00
									380.00
									120.00
									60.00
									500.00
									2400.00
									1000.00
									120.00

Confirmed & accepted by

Go Chee Han
DID : 6771 4336 HP : 9181 7717
Email : cheehan.go@cyclecarrage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMS1387Z

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

WIP No 64624
Reg No/Reg Date SMS1387Z / 12/02/2020
Date In/Mileage / 13481
Chassis No WDC1669422J6839035
Engine No 27091031942293
Make/Model MB/GLA 180 SPORT UTILITY VEH
Colour/Trim 021 191 Cosmos Blac/ 043 381 ARTICO/FabB

Vehicle & Document Information

SMS1387Z

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WA000001	Credit	28/04/2023/ 19:22	CH	371 / Go Chee Han					
					CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT				960.00
					REMOVE & REFIT LUGGAGE COMPARTMENT, TRIM, GARNISH CARPET FOR NECESSARY REPAIR. NETT				1400.00
					REMOVE & INSTALL INTERIOR SEATS, CARPET, GARNISH UNHOLSTRY ETC FOR NECESSARY REPAIR.				420.00
					TO REMOVE & REPLACE REAR EXHAUST SYSTEM. NETT				2160.00
					REMOVE REAR CARRIAGE ASSY FROM FRAME, IMPACT. REPLACE AND ASSEMBLE WHEEL BASE & ADJUST TO VEHICLE.				540.00
					TO INSPECT & CONDUCT WHEEL ALIGNMENT. NETT				560.00
					REMOVE & REPLACE REAR WINDSCREEN WITH INSTALL NETT			0.07	300.00
					SUPPLY & INSTALL 1 PC REAR WINDSCREEN HUPER OPTIK SOLAR FILM. NETT				240.00
					EXTRA WORK TO PROGRAM AND CODE SRS CONTROL UNIT (AFTER QUICK TEST)				480.00
					VEHICLE, GLASS SPLINTERS IN INTERIOR CLEAN (WITH BROKEN WINDOW)				180.00
					CAVITY PRESERVATION ON REPLACED OR REPAIRED BODY PANELS PERFORM				120.00
					BEADS, SEAMS AND FLANGES ON REPLACEMENT BODY PANELS/ COMPONENTS				25.00
					SUNDRIES				880.00
					Thinkware Q800 Pro 2CH 16GB (Include 16GB SD Card)	1.00	921.22	00.00	921.22
					LH/Front FENDER	1.00	921.22	00.00	921.22
					RH/Front FENDER	1.00	248.17	00.00	248.17
					LH/Front COVER FENDER & BUMPER AREA				

Confirmed & accepted by

Go Chee Han
DID : 6771 4336 HP : 9181 7717
Email : cheehan.go@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383

ESTIMATE FOR SMS1387Z

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information

WIP No 64624
Reg No/Reg Date SMS1387Z / 12/02/2020
Date In/Mileage / 13481
Chassis No WDC166942J6839035
Engine No 27091031942293
Make/Model MB/GLA 180 SPORT UTILITY VEH
Colour/Trim 021 191 Cosmos Blac/ 043 381 ARTICO/FabB

Account No	Terms	Date/Time Printed	CSE	Operator	
WA000001	Credit	28/04/2023/ 19:22	CH	371 / Go Chee Han	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M	RH/FRONT COVER FENDER & BUMPER AREA	1.00	248.17	00.00	248.17
M	EXPANSION RIVET	6.00	6.09	00.00	36.54
M	FRONT BUMPER	1.00	1444.89	00.00	1444.89
M	FRONT BUMPER MB EMBLEM	1.00	68.61	00.00	68.61
M	FRONT BUMPER LICENSE PLATE MOLDING	1.00	141.08	00.00	141.08
M	FRONT BUMPER LOWER SILVER TRIM	1.00	1014.67	00.00	1014.67
M	FRONT BUMPER LOWER GRILLE	1.00	165.87	00.00	165.87
M	RH/FRONT BUMPER BOTTOM BLACK TRIM	1.00	169.95	00.00	169.95
M	LH/FRONT BUMPER SIDE COVER	1.00	83.56	00.00	83.56
M	RH/FRONT BUMPER SIDE COVER	1.00	83.56	00.00	83.56
M	LH/FRONT BUMPER SIDE COVER INNER	1.00	66.72	00.00	66.72
M	TOP BASIC MOUNTING FOR FRONT BUMPER	1.00	243.46	00.00	243.46
M	FRONT BUMPER IMPACT ABSORBER	1.00	161.72	00.00	161.72
M	FRONT BUMPER ELECTRICAL WIRING HARNESS	1.00	464.27	00.00	464.27
M	FRONT MERCEDES STAR	1.00	145.89	00.00	145.89
M	FRONT MERCEDES STAR CARRIER	1.00	82.12	00.00	82.12
M	FRONT MERCEDES STAR CARRIER BEAM	1.00	132.88	00.00	132.88
M	RADIATOR GRILL BEAM	1.00	336.13	00.00	336.13
M	FRONT GRILLE TOP BEAM	1.00	237.84	00.00	237.84
M	FRONT GRILLE BOTTOM BEAM	1.00	237.84	00.00	237.84
M	TS RADIATOR GRILLE	1.00	447.15	00.00	447.15
M	LH/FRONT AIR FLOW SERRATION	1.00	88.27	00.00	88.27
M	RH/FRONT AIR FLOW SERRATION	1.00	88.27	00.00	88.27
M	LH/FRONT BUMPER INNER SUPPORT	1.00	17.25	00.00	17.25
M	RH/FRONT BUMPER INNER SUPPORT	1.00	17.25	00.00	17.25
M	ENGINE HOOD	1.00	1605.92	00.00	1605.92
M	LH/ENGINE HOOD HINGE	1.00	99.61	00.00	99.61
M	RH/ENGINE HOOD HINGE	1.00	99.61	00.00	99.61
M	LH/HEADLAMP UNIT	1.00	2696.36	00.00	2696.36
M	RH/HEADLAMP UNIT	1.00	2696.36	00.00	2696.36
M	LH/LIGHT RANGE CONTROL UNIT	1.00	870.17	00.00	870.17
M	RH/RANGE CONTROL UNIT	1.00	870.17	00.00	870.17
M	FRONT CROSS MEMBER	1.00	353.78	00.00	353.78

Confirmed & accepted by

Go Chee Han
DID : 6771 4336 HP : 9181 7717
Email : cheehan.go@cyclecarrage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg

ESTIMATE FOR SMS1387Z

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information
WIP No 64624
Reg No/Reg Date SMS1387Z / 12/02/2020
Date In/Mileage / 13481
Chassis No WDC166942J6839035
Engine No 27091031942293
Make/Model MB/GLA 180 SPORT UTILITY VEH
Colour/Trim 021 191 Cosmos Blac/ 043 381 ARTICO/FabB

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WA000001	Credit	28/04/2023/ 19:22	CH	371 / Go Chee Han					
					M FRONT SUPPORT PANEL	1.00	1080.64	00.00	1080.64
					M REFRIGERANT CONDENSER	1.00	1185.38	00.00	1185.38
					M RADIATOR	1.00	916.69	00.00	916.69
					M INFORMATION LABEL	1.00	22.12	00.00	22.12
					M ENGINE COMPARTMENT LABEL	1.00	54.03	00.00	54.03
					M LH/WATER DEFLECTOR	1.00	211.10	00.00	211.10
					M RH/WATER DEFLECTOR	1.00	211.10	00.00	211.10
					M REAR BUMPER	1.00	1225.52	00.00	1225.52
					M REAR BUMPER BOTTOM BLACK TRIM	1.00	640.85	00.00	640.85
					M REAR BUMPER BOTTOM SILVER TRIM	1.00	1108.91	00.00	1108.91
					M REAR BUMPER FOOT STEP PLATE	1.00	245.03	00.00	245.03
					M REAR BUMPER BOTTOM REINFORCEMENT	1.00	71.00	00.00	71.00
					M LH/TAI PIPE BRACKET	1.00	130.05	00.00	130.05
					M RH/TAI PIPE BRACKET	1.00	130.05	00.00	130.05
					M LH/TAI PIPE COVER	1.00	290.14	00.00	290.14
					M RH/TAI PIPE COVER	1.00	290.14	00.00	290.14
					M CUPPED BLIND RIVET	12.00	2.14	00.00	25.68
					M LH/BASIC MOUNTING FOR REAR BUMPER	1.00	73.51	00.00	73.51
					M RH/BASIC MOUNTING FOR REAR BUMPER	1.00	72.88	00.00	72.88
					M LH/REAR BUMPER BOTTOM BRACKET	1.00	77.91	00.00	77.91
					M RH/REAR BUMPER BOTTOM BRACKET	1.00	77.91	00.00	77.91
					M REAR BUMPER DISTANCE SENSOR	2.00	205.45	00.00	410.90
					M SPACER RING	6.00	7.85	00.00	47.10
					M REAR BUMPER ELECTRICAL WIRING HARNESS	1.00	134.77	00.00	134.77
					M LH/REAR BUMPER DAMPING, SIDE WALL	1.00	47.44	00.00	47.44
					M RH/REAR BUMPER DAMPING, SIDE WALL	1.00	47.44	00.00	47.44
					M TAILGATE	1.00	2459.72	00.00	2459.72
					M ADHESIVE FILM CUTTING	2.00	9.74	00.00	19.48
					M SEALING FOR TAILGATE	1.00	233.09	00.00	233.09
					M INTERMEDIATE LAYER	2.00	5.12	00.00	10.24
					M TAILGATE LOCK	1.00	306.88	00.00	306.88
					M U-SHAPED STRIKER (END PANEL)	1.00	36.72	00.00	36.72
					M TAILGATE RELEASE HANDLE	1.00	167.65	00.00	167.65

Confirmed & accepted by

Authorized signatory and company stamp

Go Chee Han
DID : 6771 4336 HP : 9181 7717
Email : cheehan.go@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMS1387Z

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information

WIP No **64624**
Reg No/Reg Date **SMS1387Z / 12/02/2020**
Date In/Mileage **/ 13481**
Chassis No **WDC1569422J6839035**
Engine No **27091031942293**
Make/Model **MB/GLA 180 SPORT UTILITY VEH**
Colour/Trim **021 191 Cosmos Blac/ 043 381 ARTICO/FabB**

Account No	Terms	Date/Time Printed	CSE	Operator
WA000001	Credit	28/04/2023/ 19:22	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M TAILGATE TRIM PANELING <i>1.50m</i>	1.00	265.45	00.00	265.45
M TAILGATE PANELING CLOSING HANDLE <i>1.50m</i>	1.00	149.84	00.00	149.84
M TAILGATE PANELING WINDOW FRAME <i>1.50m</i>	1.00	197.91	00.00	197.91
M REAR WINDOW <i>1.50m</i>	1.00	783.12	00.00	783.12
M SEALING STRIP <i>1.50m</i>	2.00	3.14	00.00	6.28
M ONE-COMPONENT ADHESIVE <i>1.50m</i>	1.00	183.81	00.00	183.81
M GLA 180 MODEL PLATE <i>1.50m</i>	1.00	103.67	00.00	103.67
M GROMMET <i>1.50m</i>	3.00	2.73	00.00	8.19
M TAILGATE MERCEDES STAR <i>1.50m</i>	1.00	52.05	00.00	52.05
M TAILGATE HATCH MOULDING <i>1.50m</i>	1.00	169.64	00.00	169.64
M GROMMET <i>1.50m</i>	3.00	2.73	00.00	8.19
M TREENAIL <i>1.50m</i>	4.00	5.97	00.00	23.88
M LH/OUTER REAR LAMP COMBINATION <i>1.50m</i>	1.00	818.42	00.00	818.42
M RH/OUTER REAR LAMP COMBINATION <i>1.50m</i>	1.00	818.42	00.00	818.42
M LH/INNER REAR LAMP COMBINATION <i>1.50m</i>	1.00	543.94	00.00	543.94
M RH/INNER REAR LAMP COMBINATION <i>1.50m</i>	1.00	543.94	00.00	543.94
M LH/INNER SEAL, LAMP HOUSING <i>1.50m</i>	1.00	15.01	00.00	15.01
M RH/INNER SEAL, LAMP HOUSING <i>1.50m</i>	1.00	15.01	00.00	15.01
M REAR END PANEL <i>1.50m</i>	1.00	1441.90	00.00	1441.90
M LH/REAR WHEEL ARCH TRIM COVER <i>1.50m</i>	1.00	262.62	00.00	262.62
M RH/REAR WHEEL ARCH TRIM COVER <i>1.50m</i>	1.00	262.62	00.00	262.62
M RH/REAR FENDER <i>1.50m</i>	1.00	2638.78	00.00	2638.78
M LH/FRONT SEAT BELT <i>1.50m</i>	1.00	632.21	00.00	632.21
M RH/FRONT SEAT BELT <i>1.50m</i>	1.00	632.21	00.00	632.21
M LH/REAR SEAT BELT <i>1.50m</i>	1.00	376.56	00.00	376.56
M RH/REAR SEAT BELT <i>1.50m</i>	1.00	376.56	00.00	376.56
M LH/REAR LOCK FOR SEAT BACKREST <i>1.50m</i>	1.00	343.44	00.00	343.44
M RH/REAR LOCK FOR SEAT BACKREST <i>1.50m</i>	1.00	348.60	00.00	348.60
M LH/REAR SEAT LOCK COVER <i>1.50m</i>	1.00	49.95	00.00	49.95
M RH/REAR SEAT LOCK COVER <i>1.50m</i>	1.00	49.95	00.00	49.95
M SRS CONTROL UNIT <i>1.50m</i>	1.00	904.72	00.00	904.72
M SRS ACCELERATION SENSOR <i>1.50m</i>	2.00	173.78	00.00	347.56
M REAR EXHAUST SHIELDING <i>1.50m</i>	1.00	147.39	00.00	147.39

Confirmed & accepted by

Go Chee Han
DID: 6771 4336 HP: 9181 7717
Email: cheehan.go@cyclecarrage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
6298 6083



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMS1387Z

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information

WIP No **64624**
Reg No/Reg Date **SMS1387Z / 12/02/2020**
Date In/Mileage **/ 13481**
Chassis No **WDC1569422J6839035**
Engine No **27091031942293**
Make/Model **MB/GLA 180 SPORT UTILITY VEH**
Colour/Trim **021 191 Cosmos Blac/ 043 381 ARTICO/FabB**

Account No	Terms	Date/Time Printed	CSE	Operator
WA000001	Credit	28/04/2023/ 19:22	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M REAR EXHAUST SYSTEM	1.00	1264.78	00.00	1264.78
M PIPE CLAMP	1.00	137.28	00.00	137.28
M TRIM REAR SHELF	1.00	1130.90	00.00	1130.90
M WHITE SEAM SEALING COMPOUND	2.00	116.42	00.00	232.84
M TS TWO-COMPONENT ADHESIVE	1.00	904.72	00.00	904.72
M TS TWO-COMPONENT ADHESIVE	1.00	904.72	00.00	904.72
M TWO-COMPONENT ADHESIVE	1.00	118.43	00.00	118.43
M CAVITY PRESERVATIVE	1.00	116.39	00.00	116.39
M ZINC DUST PAINT	1.00	66.41	00.00	66.41
M LH/REAR SPOILER ATTACHMENT	1.00	131.62	00.00	131.62
M RH/REAR SPOILER ATTACHMENT	1.00	131.62	00.00	131.62
M REAR CROSS MEMBER	1.00	669.12	00.00	669.12
M REAR WIPER MOTOR	1.00	285.80	00.00	285.80
M REAR WIPER BLADE	1.00	40.03	00.00	40.03
M REAR WIPER ARM	1.00	107.44	00.00	107.44
M REAR COVER, WIPER ARM	1.00	5.34	00.00	5.34

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Go Chee Han

DID : 6771 4336 HP : 9181 7717

Email : cheehan.go@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

Confirmed & accepted by

Nett **86,472.90**
8% GST on **86472.90** **6917.83**

Total Payable **93,390.73**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg