

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	28/04/2023 14:38 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	24/04/2023 16:31 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	ZION ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMS1387Z
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TAN YANG HWEE
NRIC No	SXXXXX011I
Email Address	YANG_TANN@YAHOO.COM.SG
Mobile Phone No	(Phone) +65-96770763
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	Gla180
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1595

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Policy Number / Cover Note Number	2070014277-03

DRIVER

Name of Driver	TAN YANG HWEE
NRIC No	SXXXXX011I
Date Of Birth	19/02/1955
Occupation	Indoor

Date Of Driving Pass	26/01/1985
Driving experience	38 YEARS AND 3 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96770763
Alt. Phone Number	-
Email Address	YANG_TANN@YAHOO.COM.SG
Address	329A THOMSON ROAD #02-08
Address complement	-
Postcode	307686
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	Yes
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	YEO SEN LU
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Orchard Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18007359999
Alt. Police Station Phone No	(Fax) +65-67331934
Police Station Address	51 Killiney Road Singapore 239572
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT NO: T/20230425/2028

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	WITH TP

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YR1G
Vehicle Manufacturer	Hino
Vehicle Model	XZU710R
Vehicle Variant	-
Vehicle Colour	White
Vehicle Category	Commercial vehicle
Name of Driver	ZENG QIANG
Passport No/FIN	GXXXX005R
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	Allianz Insurance Singapore Pte. Ltd.
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GBD7842X
Vehicle Manufacturer	Toyota
Vehicle Model	Hiace
Vehicle Variant	-
Vehicle Colour	White
Vehicle Category	Commercial vehicle
Name of Driver	JUSTIN LIM CHUNG KING
Passport No/FIN	SXXXX929J
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	TAN YANG HWEE
Gender	Male
Phone No	(Phone) +65-96770763
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SMS1387Z
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	Yes

INJURED 2

Name of injured person	YEO SEN LU
Gender	Female
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SMS1387Z
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	Yes

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :


- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Go Chee Han
DID : 6771 4336 HP : 9181 7717
Email : cheehan.go@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop


Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

Refer to police report: T/20230425/2028

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

Go Chee Han
DID : 6771 4336 HP : 9181 7717
Email : cheehan.go@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop



SINGAPORE POLICE FORCE



T/20230425/2028

Police Station Of Origin:
Orchard N.P.C
51 Killiney Road SINGAPORE 239572
Tel No: 1800-7359999

1 of 4

Report No. T/20230425/2028

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 25/04/2023 11:47	Vide Report No.: E/20230424/0096	Station Diary No.: 51
--	-------------------------------------	--------------------------

Informant's Particulars				
Name of Informant: TAN YANG HWEE			Address: 329A THOMSON ROAD #02-08 SINGAPORE 307686	
ID Type / ID No.: NRIC NO / S11130111			Contact No.: Home/Office: Mobile: 96770763	
Nationality: SINGAPORE CITIZEN			Email: yang_tann@yahoo.com.sg	
Sex: Male	Age: 68	Date of Birth: 19/02/1955	Type of Informant: Driver	
Race: Chinese			Language:	
Occupation: Retiree			Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 24/04/2023 16:30	Type of Location: Straight Road
Location: ZION ROAD				
Weather: Drizzling		Road Surface: Wet		
Traffic Flow: One Way		Traffic Control:		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBD7842X	Van			White	Slightly Damaged	0
SMS1387Z	Car	MERCEDES BENZ	GLA180 URBAN (R18 LED)	Black	Seriously Damaged	1
YR1G	Lorry			White	Seriously Damaged	0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date



**SINGAPORE
POLICE FORCE**



T/20230425/2028

2 of 4

Police Station Of Origin:
Orchard N.P.C
51 Killiney Road SINGAPORE 239572
Tel No: 1800-7359999

Report No. T/20230425/2028

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SMS1387Z	AIG ASIA PACIFIC INSURANCE PTE. LTD.	2070014277-03	12/02/2023	11/02/2024

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	Justin Lim Chung King		ID No.	S7428929J
Related Vehicle	NIL		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	TAN YANG HWEE		ID No.	S1113011I
Related Vehicle	NIL		Contact No.	96770763
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	Zeng Qiang		ID No.	G8523005R
Related Vehicle	NIL		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL



**SINGAPORE
POLICE FORCE**



T/20230425/2028

Police Station Of Origin:
Orchard N.P.C
51 Killiney Road SINGAPORE 239572
Tel No: 1800-7359999

3 of 4

Report No. T/20230425/2028

CONTINUATION OF REPORT

Brief Details.

On 24/04/2023 at 1631hrs, I was driving at the second lane from the left with my wife at the seat beside me when suddenly a lorry (YR1G) collided with me from the back which caused my vehicle (SMS1387Z) to go forward and collided with a van (GBD7842X) ahead of me. All 3 vehicles then stopped however, as my vehicle was sandwiched in between both vehicles, my front bumper got bent in and my rear bumper also got knocked inwards causing my driver door and passenger door to be stuck and unable to open. I managed to force my door open and was conveyed to Singapore General hospital together with my wife.

I managed to exchange details with both drivers and was attended by police vide E/20230424/0096. I suffered minor pain at the back of my neck while my wife suffered chest pain and was only discharge from hospital at about 2100hrs.

I wish to state my vehicle was tolled to Traffic police. I was advised by TP personnel Esmond to lodge a report.



**SINGAPORE
POLICE FORCE**



T/20230425/2028

Police Station Of Origin:
Orchard N.P.C
51 Killiney Road SINGAPORE 239572
Tel No: 1800-7359999

4 of 4

Report No. T/20230425/2028

CONTINUATION OF REPORT

Signature of Officer Recording The Report:

E /

SGT 2 Tan Junwei

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

25/04/2023 11:47

Officer In Charge Of Case:

TP / GIT /

SGT 2 PHUA TIAK YEE

Contact No.: 65476200

Classification Of Case:



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMS1387Z

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information

WIP No **64624**
Reg No/Reg Date **SMS1387Z / 12/02/2020**
Date In/Mileage **/ 13481**
Chassis No **WDC1569422J6839035**
Engine No **27091031942293**
Make/Model **MB/GLA 180 SPORT UTILITY VEH**
Colour/Trim **021 191 Cosmos Blac/ 043 381 ARTICO/FabB**

Account No	Terms	Date/Time Printed	CSE	Operator				
WA000001	Credit	28/04/2023/ 19:22	CH	371 / Go Chee Han				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z REQUEST								
Customer Request								
M BPNSUN								
POLICY NO/ACC DATE : 2070014277-03 // 24-4-2023								
TOW IN/TP VEH NUMBER : 28-4-2023 // YR1G - ALLIANZ								
DATE IN/DATE SURVEY:								
DIRECT SETTLEMENT BY:								
S BPNTOW								150.00
ACCIDENT TOWING FROM 517 AIRPORT ROAD TO PLSC								
USING: KING DOLLEY								
REFER WO: 1319529								
A BPILAB								14400.00
PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW								
BODY PANELS AND REFINISH.								9600.00
A BPIRES								
RESPRAY FRONT BUMPER & ENGINE HOOD & LH/Front FENDER & RH/Front FENDER								
REAR BUMPER & TAILGATE & LH/REAR FENDER & RH/REAR FENDER & END PANEL								
REAR SPOILER & LH/Front DOOR & RH/Front DOOR								
A BPILAB							0.10	380.00
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO								
IDENTIFICATION STANDARD. NETT								120.00
A BPILAB								
TO REMOVE, REPLACE HEADLAMP WITH FOCUS . NETT								60.00
S BPNSUB								
SUPPLY 1 SET FRONT NUMBER PLATE WITH HOUSING. NETT								
A BPILAB							0.07	500.00
REMOVE, REPLACE RADIATOR, CONDENSER COOLING SYSTEM & FITTINGS-								
VACUUM AND REGAS . NETT								2400.00
A BPILAB								
TO REMOVE/REPLACE AFFECTED SEAT BELTS								
A BPILAB							0.07	1000.00
PLACE VEHICLE ON-TO CELLETTE BENCH & CONDUCT CHASSIS ALIGNMENT. NETT								120.00
A BPILAB								

Confirmed & accepted by

Go Chee Han
DID : 6771 4336 HP : 9181 7717
Email : cheehan.go@cyclecarrriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMS1387Z

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information

WIP No **64624**
Reg No/Reg Date **SMS1387Z / 12/02/2020**
Date In/Mileage **/ 13481**
Chassis No **WDC1569422J6839035**
Engine No **27091031942293**
Make/Model **MB/GLA 180 SPORT UTILITY VEH**
Colour/Trim **021 191 Cosmos Blac/ 043 381 ARTICO/FabB**

Account No	Terms	Date/Time Printed	CSE	Operator				
WA000001	Credit	28/04/2023/ 19:22	CH	371 / Go Chee Han				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT								960.00
A BPILAB REMOVE & REFIT LUGGAGE COMPARTMENT, TRIM, GARNISH-CARPET FOR NECESSARY REPAIR. NETT								1440.00
A BPILAB REMOVE & INSTALL INTERIOR SEATS, CARPET, GARNISH UNHOLSTRY ETC FOR NECESSARY REPAIR.								420.00
A BPILAB TO REMOVE & REPLACE REAR EXHAUST SYSTEM. NETT								2160.00
A BPILAB REMOVE REAR CARRIAGE ASSY FROM FRAME, IMPACT. REPLACE AND ASSEMBLE WHEEL BASE & ADJUST TO VEHICLE.								540.00
A BPILAB TO INSPECT & CONDUCT WHEEL ALIGNMENT. NETT							0.07	560.00
A BPILAB REMOVE & REPLACE REAR WINDSCREEN WITH INSTALL. NETT								300.00
S BPNSUB SUPPLY & INSTALL 1 PC REAR WINDSCREEN HUPER OPTIK SOLAR FILM. NETT								240.00
A BPILAB EXTRA WORK TO PROGRAM AND CODE SRS CONTROL UNIT (AFTER QUICK TEST)								480.00
A 67125001 VEHICLE, GLASS SPLINTERS IN INTERIOR CLEAN (WITH BROKEN WINDOW)								180.00
A 97250001 CAVITY PRESERVATION ON REPLACED OR REPAIRED BODY PANELS PERFORM								120.00
A 97510101 BEADS, SEAMS AND FLANGES ON REPLACEMENT BODY PANELS/ COMPONENTS								25.00
M BPNSUN SUNDRIES								880.00
S DVRF800PRO2CH Thinkware Q800 Pro 2CH 16GB (Include 16GB SD Card)					1.00	921.22	00.00	921.22
M LH/FRONT FENDER					1.00	921.22	00.00	921.22
M RH/FRONT FENDER					1.00	248.17	00.00	248.17
M LH/FRONT COVER FENDER & BUMPER AREA								

Go Chee Han

Confirmed & accepted by

DID : 6771 4336 HP : 9181 7717
Email : cheehan.go@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMS1387Z

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information

WIP No **64624**
Reg No/Reg Date **SMS1387Z / 12/02/2020**
Date In/Mileage **/ 13481**
Chassis No **WDC1569422J6839035**
Engine No **27091031942293**
Make/Model **MB/GLA 180 SPORT UTILITY VEH**
Colour/Trim **021 191 Cosmos Blac/ 043 381 ARTICO/FabB**

Account No	Terms	Date/Time Printed	CSE	Operator				
WA000001	Credit	28/04/2023/ 19:22	CH	371 / Go Chee Han				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	RH/FRONT COVER FENDER & BUMPER AREA				1.00	248.17	00.00	248.17
M	EXPANSION RIVET				6.00	6.09	00.00	36.54
M	FRONT BUMPER				1.00	1444.89	00.00	1444.89
M	FRONT BUMPER MB EMBLEM				1.00	68.61	00.00	68.61
M	FRONT BUMPER LICENSE PLATE MOLDING				1.00	141.08	00.00	141.08
M	FRONT BUMPER LOWER SILVER TRIM				1.00	1014.67	00.00	1014.67
M	FRONT BUMPER LOWER GRILLE				1.00	165.87	00.00	165.87
M	RH/FRONT BUMPER BOTTOM BLACK TRIM				1.00	169.95	00.00	169.95
M	LH/FRONT BUMPER SIDE COVER				1.00	83.56	00.00	83.56
M	RH/FRONT BUMPER SIDE COVER				1.00	83.56	00.00	83.56
M	LH/FRONT BUMPER SIDE COVER INNER				1.00	66.72	00.00	66.72
M	TOP BASIC MOUNTING FOR FRONT BUMPER				1.00	243.46	00.00	243.46
M	FRONT BUMPER IMPACT ABSORBER				1.00	161.72	00.00	161.72
M	FRONT BUMPER ELECTRICAL WIRING HARNESS				1.00	464.27	00.00	464.27
M	FRONT MERCEDES STAR				1.00	145.89	00.00	145.89
M	FRONT MERCEDES STAR CARRIER				1.00	82.12	00.00	82.12
M	FRONT MERCEDES STAR CARRIER BEAM				1.00	132.88	00.00	132.88
M	RADIATOR GRILL BEAM				1.00	336.13	00.00	336.13
M	FRONT GRILLE TOP BEAM				1.00	237.84	00.00	237.84
M	FRONT GRILLE BOTTOM BEAM				1.00	237.84	00.00	237.84
M	TS RADIATOR GRILLE				1.00	447.15	00.00	447.15
M	LH/FRONT AIR FLOW SERRATION				1.00	88.27	00.00	88.27
M	RH/FRONT AIR FLOW SERRATION				1.00	88.27	00.00	88.27
M	LH/FRONT BUMPER INNER SUPPORT				1.00	17.25	00.00	17.25
M	RH/FRONT BUMPER INNER SUPPORT				1.00	17.25	00.00	17.25
M	ENGINE HOOD				1.00	1605.92	00.00	1605.92
M	LH/ENGINE HOOD HINGE				1.00	99.61	00.00	99.61
M	RH/ENGINE HOOD HINGE				1.00	99.61	00.00	99.61
M	LH/HEADLAMP UNIT				1.00	2696.36	00.00	2696.36
M	RH/HEADLAMP UNIT				1.00	2696.36	00.00	2696.36
M	LH/LIGHT RANGE CONTROL UNIT				1.00	870.17	00.00	870.17
M	RH/RANGE CONTROL UNIT				1.00	870.17	00.00	870.17
M	FRONT CROSS MEMBER				1.00	353.78	00.00	353.78

Confirmed & accepted by

Go Chee Han
DID : 6771 4336 HP : 9181 7717
Email : cheehan.go@cyclicarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMS1387Z

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information

WIP No **64624**
Reg No/Reg Date **SMS1387Z / 12/02/2020**
Date In/Mileage **/ 13481**
Chassis No **WDC1569422J6839035**
Engine No **27091031942293**
Make/Model **MB/GLA 180 SPORT UTILITY VEH**
Colour/Trim **021 191 Cosmos Blac/ 043 381 ARTICO/FabB**

Account No	Terms	Date/Time Printed	CSE	Operator	
WA000001	Credit	28/04/2023/ 19:22	CH	371 / Go Chee Han	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M	FRONT SUPPORT PANEL	1.00	1080.64	00.00	1080.64
M	REFRIGERANT CONDENSER	1.00	1185.38	00.00	1185.38
M	RADIATOR	1.00	916.69	00.00	916.69
M	INFORMATION LABEL	1.00	22.12	00.00	22.12
M	ENGINE COMPARTMENT LABEL	1.00	54.03	00.00	54.03
M	LH/WATER DEFLECTOR	1.00	211.10	00.00	211.10
M	RH/WATER DEFLECTOR	1.00	211.10	00.00	211.10
M	REAR BUMPER	1.00	1225.52	00.00	1225.52
M	REAR BUMPER BOTTOM BLACK TRIM	1.00	640.85	00.00	640.85
M	REAR BUMPER BOTTOM SILVER TRIM	1.00	1108.91	00.00	1108.91
M	REAR BUMPER FOOT STEP PLATE	1.00	245.03	00.00	245.03
M	REAR BUMPER BOTTOM REINFORCEMENT	1.00	71.00	00.00	71.00
M	LH/TAIL PIPE BRACKET	1.00	130.05	00.00	130.05
M	RH/TAIL PIPE BRACKET	1.00	130.05	00.00	130.05
M	LH/TAIL PIPE COVER	1.00	290.14	00.00	290.14
M	RH/TAIL PIPE COVER	1.00	290.14	00.00	290.14
M	CUPPED BLIND RIVET	12.00	2.14	00.00	25.68
M	LH/BASIC MOUNTING FOR REAR BUMPER	1.00	73.51	00.00	73.51
M	RH/BASIC MOUNTING FOR REAR BUMPER	1.00	72.88	00.00	72.88
M	LH/REAR BUMPER BOTTOM BRACKET	1.00	77.91	00.00	77.91
M	RH/REAR BUMPER BOTTOM BRACKET	1.00	77.91	00.00	77.91
M	REAR BUMPER DISTANCE SENSOR	2.00	205.45	00.00	410.90
M	SPACER RING	6.00	7.85	00.00	47.10
M	REAR BUMPER ELECTRICAL WIRING HARNESS	1.00	134.77	00.00	134.77
M	LH/REAR BUMPER DAMPING, SIDE WALL	1.00	47.44	00.00	47.44
M	RH/REAR BUMPER DAMPING, SIDE WALL	1.00	47.44	00.00	47.44
M	TAILGATE	1.00	2459.72	00.00	2459.72
M	ADHESIVE FILM CUTTING	2.00	9.74	00.00	19.48
M	SEALING FOR TAILGATE	1.00	233.09	00.00	233.09
M	INTERMEDIATE LAYER	2.00	5.12	00.00	10.24
M	TAILGATE LOCK	1.00	306.88	00.00	306.88
M	U-SHAPED STRIKER (END PANEL)	1.00	36.72	00.00	36.72
M	TAILGATE RELEASE HANDLE	1.00	167.65	00.00	167.65

Confirmed & accepted by

Authorized signatory and company stamp

Go Chee Han
DID : 6771 4336 HP : 9181 7717
Email : cheehan.go@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMS1387Z

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information

WIP No 64624
Reg No/Reg Date SMS1387Z / 12/02/2020
Date In/Mileage / 13481
Chassis No WDC1569422J6839035
Engine No 27091031942293
Make/Model MB/GLA 180 SPORT UTILITY VEH
Colour/Trim 021 191 Cosmos Blac/ 043 381 ARTICO/FabB

Account No	Terms	Date/Time Printed	CSE	Operator	
WA000001	Credit	28/04/2023/ 19:22	CH	371 / Go Chee Han	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M	TAILGATE TRIM PANELING	1.00	265.45	00.00	265.45
M	TAILGATE PANELING CLOSING HANDLE	1.00	149.84	00.00	149.84
M	TAILGATE PANELING WINDOW FRAME	1.00	197.91	00.00	197.91
M	REAR WINDOW	1.00	783.12	00.00	783.12
M	SEALING STRIP	2.00	3.14	00.00	6.28
M	ONE-COMPONENT ADHESIVE	1.00	183.81	00.00	183.81
M	GLA 180 MODEL PLATE	1.00	103.67	00.00	103.67
M	GROMMET	3.00	2.73	00.00	8.19
M	TAILGATE MERCEDES STAR	1.00	52.05	00.00	52.05
M	TAILGATE HATCH MOULDING	1.00	169.64	00.00	169.64
M	GROMMET	3.00	2.73	00.00	8.19
M	TREENAIL	4.00	5.97	00.00	23.88
M	LH/OUTER REAR LAMP COMBINATION	1.00	818.42	00.00	818.42
M	RH/OUTER REAR LAMP COMBINATION	1.00	818.42	00.00	818.42
M	LH/INNER REAR LAMP COMBINATION	1.00	543.94	00.00	543.94
M	RH/INNER REAR LAMP COMBINATION	1.00	543.94	00.00	543.94
M	LH/INNER SEAL, LAMP HOUSING	1.00	15.01	00.00	15.01
M	RH/INNER SEAL, LAMP HOUSING	1.00	15.01	00.00	15.01
M	REAR END PANEL	1.00	1441.90	00.00	1441.90
M	LH/REAR WHEEL ARCH TRIM COVER	1.00	262.62	00.00	262.62
M	RH/REAR WHEEL ARCH TRIM COVER	1.00	262.62	00.00	262.62
M	RH/REAR FENDER	1.00	2638.78	00.00	2638.78
M	LH/FRONT SEAT BELT	1.00	632.21	00.00	632.21
M	RH/FRONT SEAT BELT	1.00	632.21	00.00	632.21
M	LH/REAR SEAT BELT	1.00	376.56	00.00	376.56
M	RH/REAR SEAT BELT	1.00	376.56	00.00	376.56
M	LH/REAR LOCK FOR SEAT BACKREST	1.00	343.44	00.00	343.44
M	RH/REAR LOCK FOR SEAT BACKREST	1.00	348.60	00.00	348.60
M	LH/REAR SEAT LOCK COVER	1.00	49.95	00.00	49.95
M	RH/REAR SEAT LOCK COVER	1.00	49.95	00.00	49.95
M	SRS CONTROL UNIT	1.00	904.72	00.00	904.72
M	SRS ACCELERATION SENSOR	2.00	173.78	00.00	347.56
M	REAR EXHAUST SHIELDING	1.00	147.39	00.00	147.39

Confirmed & accepted by

Go Chee Han
DID : 6771 4336 HP : 9181 7717
Email : cheehan.go@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMS1387Z

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information

WIP No **64624**
Reg No/Reg Date **SMS1387Z / 12/02/2020**
Date In/Mileage **/ 13481**
Chassis No **WDC1569422J6839035**
Engine No **27091031942293**
Make/Model **MB/GLA 180 SPORT UTILITY VEH**
Colour/Trim **021 191 Cosmos Blac/ 043 381 ARTICO/FabB**

Account No	Terms	Date/Time Printed	CSE	Operator
WA000001	Credit	28/04/2023/ 19:22	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M REAR EXHAUST SYSTEM	1.00	1264.78	00.00	1264.78
M PIPE CLAMP	1.00	137.28	00.00	137.28
M TRIM REAR SHELF	1.00	1130.90	00.00	1130.90
M WHITE SEAM SEALING COMPOUND	2.00	116.42	00.00	232.84
M TS TWO-COMPONENT ADHESIVE	1.00	904.72	00.00	904.72
M TS TWO-COMPONENT ADHESIVE	1.00	904.72	00.00	904.72
M TWO-COMPONENT ADHESIVE	1.00	118.43	00.00	118.43
M CAVITY PRESERVATIVE	1.00	116.39	00.00	116.39
M ZINC DUST PAINT	1.00	66.41	00.00	66.41
M LH/REAR SPOILER ATTACHMENT	1.00	131.62	00.00	131.62
M RH/REAR SPOILER ATTACHMENT	1.00	131.62	00.00	131.62
M REAR CROSS MEMBER	1.00	669.12	00.00	669.12
M REAR WIPER MOTOR	1.00	285.80	00.00	285.80
M REAR WIPER BLADE	1.00	40.03	00.00	40.03
M REAR WIPER ARM	1.00	107.44	00.00	107.44
M REAR COVER, WIPER ARM	1.00	5.34	00.00	5.34

Go Chee Han
DID : 6771 4336 HP : 9181 7717
Email : cheehan.go@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Confirmed & accepted by

Nett 86,472.90
8% GST on 86472.90 6917.83
Total Payable 93,390.73

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG