

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 27.04.2023

TO : **LONPAC** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLG9089G**
MODEL : **KIA CERATO K3**
DATE OF ACCIDENT : 26.04.2023
TIME OF ACCIDENT : 15:00 HOURS

KNAFX411MH 5668585

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT DOOR VIEW MIRROR RH <i>End.</i>	1	\$ 1,185.00	\$ 1,185.00
2	FRONT DOOR RH <i>Distorted</i>	1	\$ 1,477.00	\$ 1,477.00
3	FRONT DOOR STICKER RH (BLACK) <i>new</i>	1	\$ 85.00	\$ 85.00
4	FRONT DOOR POWER WINDOW MOTOR RH <i>End</i>	1	\$ 770.00	\$ 770.00
5	FRONT DOOR REGULATOR RH <i>End</i>	1	\$ 385.00	\$ 385.00
6	FRONT DOOR GLASS RH <i>Shattered</i>	1	\$ 685.00	\$ 685.00
7	FRONT DOOR GLASS CHANNEL RH <i>new</i>	1	\$ 138.00	\$ 138.00
8	FRONT DOOR STEP PANEL GARNISH RH <i>new</i>	1	\$ 285.00	\$ 285.00
9	FRONT DOOR PILLAR RH <i>Regis</i>	1	\$ 986.00	\$ 986.00
10	FRONT DOOR PILLAR GLASS RH <i>new</i>	1	\$ 285.00	\$ 285.00
11	FRONT DOOR PILLAR LOWER INNER GARNISH RH	1	\$ 367.00	\$ 367.00
12	FRONT FRAME WEATHER STRIP RH <i>new</i>	1	\$ 177.00	\$ 177.00
13	FRONT DOOR OUTER HANDLE RH <i>End</i>	1	\$ 385.00	\$ 385.00
14	FRONT DOOR OUTER KEY LOCK RH <i>new</i>	1	\$ 294.00	\$ 294.00
15	FRONT DOOR OUTER MOULDING RH <i>Delid</i>	1	\$ 110.00	\$ 110.00
16	FRONT DOOR HINGE RH <i>new</i>	2	\$ 45.00	\$ 90.00
17	FRONT DOOR WEATHER STRIP RH <i>new</i>	1	\$ 160.00	\$ 160.00
18	FRONT DOOR INNER LOCK RH <i>Jammed</i>	1	\$ 480.00	\$ 480.00
19	FRONT DOOR INNER LOCK HANDLE RH <i>new</i>	1	\$ 55.00	\$ 55.00
20	FRONT DOOR LOCK CATCH RH <i>new</i>	1	\$ 23.00	\$ 23.00
21	FRONT DOOR INNER TRIM RH <i>Delid</i>	1	\$ 850.00	\$ 850.00

883

1277

368

858

TO : LONPAC MOTOR CLAIMS DEPTS
 VEHICLE NO : SLG9089G
 MODEL : KIA CERATO K3
 DATE OF ACCIDENT : 26.04.2023
 TIME OF ACCIDENT : 15:00 HOURS

22	FRONT DOOR SPEAKER RH <i>included</i>	1	\$ 298.00	\$ 298.00	<i>150(SN)</i>
23	FRONT DOOR INNER SWITCH PANEL RH <i>included</i>	1	\$ 968.00	\$ 968.00	<i>+ 685</i>
24	FRONT DOOR STOPPER RH <i>new</i>	1	\$ 35.00	\$ 35.00	<i>+</i>
25	FRONT DOOR FRAME WEATHERSTRIP RH <i>new</i>	1	\$ 174.00	\$ 174.00	<i>+</i>
26	DASHBOARD <i>new ut</i>	1	\$ 1,988.00	\$ 1,988.00	<i>+ 1072</i>
27	DASHBOARD LOWER COVER RH <i>new</i>	1	\$ 385.00	\$ 385.00	<i>+</i>
28	DASHBOARD SIDE COVER RH <i>new</i>	1	\$ 195.00	\$ 195.00	<i>+</i>
29	DASHBOARD REINFORCEMENT <i>new</i>	1	\$ 1,233.00	\$ 1,233.00	<i>+</i>
30	CENTER PILLAR (OUTER) RH <i>Dashed Paint</i>	1	\$ 1,453.00	\$ 1,453.00	<i>+ 685X</i>
31	CENTER PILLAR INNER GARNISH RH <i>new</i>	1	\$ 362.00	\$ 362.00	<i>+</i>
32	FRONT WINDSCREEN MOULDING <i>new</i>	1	\$ 225.00	\$ 225.00	<i>+</i>
33	DRIVER SEAT <i>new</i>	1	\$ 2,896.00	\$ 2,896.00	<i>+</i>

7073 S.N: 150
636570

TOTAL PRICE \$ 19,484.00
 LESS 10% \$ 1,948.40
 SUB TOTAL PRICE \$ 17,535.60

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT DOOR OUTER MOULDING CLIP RH (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
2	FRONT DOOR TRIM BOARD CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
3	FRONT STEP GARNISH CLIP <i>new</i>	1	\$ 30.00	\$ 30.00
4	DASHBOARD CLIP <i>new</i>	1	\$ 80.00	\$ 80.00
5	FRONT DOOR PILLAR LOWER GARNISH CLIP <i>new</i>	1	\$ 30.00	\$ 30.00
6	CENTER PILLAR INNER GARNISH CLIP <i>new</i>	1	\$ 50.00	\$ 50.00
7	FRONT WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00
8	FRONT WINDSCREEN INNER SHIELD <i>new</i>	1	\$ 80.00	\$ 80.00
9	FRONT WHEEL TYRE RH <i>new</i>	1	\$ 380.00	\$ 380.00

TOTAL \$ 430.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,000.00	<i>500</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	<i>600</i>

TO : LONPAC MOTOR CLAIMS DEPTS
 VEHICLE NO : SLG9089G
 MODEL : KIA CERATO K3
 DATE OF ACCIDENT : 26.04.2023
 TIME OF ACCIDENT : 15:00 HOURS

3	TUFF COAT	\$ 250.00	80.
4	WIRING CHECK	\$ 180.00	30.
5	TRANSFER FRONT DOOR MECHANISM RH	\$ 80.00	40
6	REMOVE AND REFIX FRONT WINDOW GLASS	\$ 80.00	40.
7	REMOVE AND REFIX FRONT WINDSCREEN	\$ 120.00	x.
8	REMOVE AND REFIX FRONT PILLAR GLASS	\$ 80.00	x.
9	REMOVE AND REFIX ROOF LINING & SEAT	\$ 200.00	80.
10	REMOVE AND REFIX DASHBOARD	\$ 650.00	x 220.
11	CONDUCT WATER LEAKAGE TEST	\$ 120.00	x
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x.

TOTAL \$ 5,540.00

ESTIMATE REPORT

TOTAL PARTS COST \$ 17,965.60
 TOTAL LABOUR COST : \$ 5,540.00
 TOTAL REPAIR COST : \$ 23,505.60

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
 PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR

IRENE

HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Cj
 1/s 28/04/23.

05 Days.

total: 8145.70

1/s - 6:5K

1590