



Auto 101 LLP

No. 2 Yishun Industrial St 1  
Northpoint Bizhub, #02-01  
Singapore 768159  
Tel: 67545101

DATE: 28-4-2023

REPAIR ESTIMATE

VEHICLE: SKZ4509G  
MODEL: Hyundai Elantra

S/n	Description of part	Qty	Qty
1	Rear fender RH DT	1	1857.00 ✓
2	Rear bumper SCR	1	494.00 ✓
3	Rear bumper side retainer RH ? NN	1	34.00 X
4	Rear shock absorber RH ? NN	1	239.00 X
5	Rear shock absorber mounting RH ? NN	1	30.00 X
6	Rear door handle RH SCR	1	243.00 179.10
7	Rear door handle cap RH SCR	1	54.00 ✓
8	Rear tail lamp RH SCR	1	299.00 ✓
		<b>Sub-total 1</b>	<u>3,250.00</u> 2883.1
		<b>less 20% discount</b>	<u>2,437.50</u> 2306.48
9	Sports rim RH SCR	1	850.00 600
10	Windscreen sealant NEC	1	50.00 40
11	windscreen primer NEC	1	30.00 ✓
12	Windscreen support sponge NEC	1	30.00 ✓
13	Reverse sensor X NN	1	200.00 X
		<b>Sub-total 2</b>	<u>1,198.00</u> 700
		<b>Parts total</b>	<u>3,635.50</u> 3006.48
<b>Labour</b>			
14	To straighten and panel beat rear RH frame members. To remove and refit above parts.		1200.00 600
15	To remove and refit windscreen to facilitate repair		150.00 50 120
16	To remove and replace under carriage		150.00 X 120
17	To conduct electronic alignment		120.00 80
18	To putty, re-spray painting and polish rear affected areas.		900.00 450 600
19	To rust proof affected rear areas.		80.00 X
20	To check and rectify wiring system		40.00 70
		<b>Labour total</b>	<u>2,640.00</u> 1550
		<b>Part and Labour total</b>	<u>6,275.50</u> 4556.48

05 days   
 Akid 8700 5631  
 28104123 1135